





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-07

Pictures 24

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



EK63WOU report date: 2024-03-29

MOT history

MOT expiry date	2024-06-10
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #10	2023-06-08 10:22
MOT test number	359846911424
Result	✓ Passed
Next expiry date	2024-06-10

MOT #9		2023-06-08 10:22
MOT test number		123704104693
Result		× Failed
Pass with rectification	Headlamp aim too high (4.1.2 (a))	

MOT #8	2022-06-08 09:01
MOT test number	514159948385
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-06-11 08:25
MOT test number	656019869031
Result	✓ Passed
Advice Parking brake efficiency only just met. It would appear that the braking syst adjustment or repair. (1.4.2 (a) (i))	tem requires

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #6	2020-06-10 13:24
MOT test number	566785866687
Result	✓ Passed
MOT #5	2019-06-03 11:43
MOT test number	125377199512
Result	✓ Passed
MOT #4	2017-10-11 17:00
MOT test number	930114868060
Result	✓ Passed
Advice No smoke reading(clean engine)	

MOT #3	2017-10-11 14:46
MOT test number	179084220164
Result	× Failed
Fail Nearside Headlamp not working on dipped beam (1.7.5a) Advice No smoke reading(clean engine)	
Fail Brake hydraulic reservoir cap missing (3.6.G.1a)	

MOT #2		2016-10-03 11:18
MOT test	number	854851104015
Result		✓ Passed
Advice	No smoke reading(clean engine)	
Advice	Vehicles internal headlight adjuster altered to recheck lights	

MOT #1	2016-05-20 12:03
MOT test number	309692691500
Result	✓ Passed

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK NEZ
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-29
Last registration	2023-06-08
Complete history	See info



Registration #1	2013-10-29	10 mi
Registration #2	2016-05-20	44.777 mi
Registration #3	2016-10-03	60.314 mi
Registration #4	2017-10-11	102.449 mi
Registration #5	2017-10-11	102.449 mi
Registration #6	2019-06-03	113.951 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	8 page 10/10