



**DG60ZHB**

report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SPORT
Colour	Silver
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-08
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-10-02
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	19
Total items failed	0

MOT #12	2022-10-03 15:02
MOT test number	453068139373
Result	✓ Passed
Next expiry date	2023-10-02
Advice	Items removed from driver's view prior to test
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	General underside corrosion

MOT #11	2022-09-30 14:50
MOT test number	780603341909
Result	✗ Failed
Advice	General underside corrosion
MAJOR	Nearside Front Body component damaged and likely to cause injury foglight (6.2.1 (a) (i))
Advice	Items removed from driver's view prior to test
MAJOR	Nearside Position lamp not working (4.2.1 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Front Brakes imbalanced across an axle (1.2.1 (b) (i))

**MOT #10** 2021-10-01 14:04**MOT test number** 525878972975**Result** ✓ Passed

**Minor** Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened o/s n/s will need attention soon (1.1.14 (a) (ii))

**Minor** Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** General underside surface corrosion not affecting structural rigidity

**MOT #9** 2020-09-12 10:41**MOT test number** 194599353798**Result** ✓ Passed**MOT #8** 2020-09-12 08:38**MOT test number** 735625205711**Result** ✗ Failed

**MAJOR** Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Both front (5.2.3 (d) (i))

**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #7** 2019-09-21 09:09**MOT test number** 364011938108**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Nearside Rear tyre slightly misshaped

**MOT #6** 2018-09-22 12:11**MOT test number** 916906960051**Result** ✓ Passed



<b>MOT #5</b>	2017-09-16 08:21
---------------	------------------

<b>MOT test number</b>	623404287471
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>MOT #4</b>	2016-08-31 11:36
---------------	------------------

<b>MOT test number</b>	212930915187
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-09-21 10:46
---------------	------------------

<b>MOT test number</b>	201212108032
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-09-16 12:33
---------------	------------------

<b>MOT test number</b>	995489354200
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2013-09-25 10:38
---------------	------------------

<b>MOT test number</b>	208578763255
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-09-28
Last registration	2022-10-03
Complete history	<a href="#">See info</a>



Registration #1	2010-09-28	7 mi
Registration #2	2013-09-25	34.679 mi
Registration #3	2014-09-16	40.910 mi
Registration #4	2015-09-21	47.752 mi
Registration #5	2016-08-31	54.867 mi
Registration #6	2017-09-16	79.513 mi
Registration #7	2018-09-22	114.526 mi
Registration #8	2019-09-22	151.277 mi
Registration #9	2020-09-22	188.028 mi
Registration #10	2021-09-22	224.779 mi
Registration #11	2022-09-22	261.530 mi
Registration #12	2023-09-22	298.281 mi
Registration #13	2024-09-22	335.032 mi
Registration #14	2025-09-22	371.783 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1555 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10241636