



E0IOYNC

report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg





Internet history

Entry 1

Date	2021-10-17
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #16	2022-10-17 14:04
MOT test number	877114675806
Result	✓ Passed
Next expiry date	2023-10-17
Advice	Tyre worn close to legal limit/worn on edge Both rear on inner edge (5.2.3 (e))

MOT #15	2021-10-18 14:35
MOT test number	371582666046
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14	2020-10-08 08:27
MOT test number	147623799352
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2020-10-07 12:45
MOT test number	661337159508
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
DANGEROUS	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Bonnet cannot be secured in the closed position (3.1 (b) (i))

**MOT #12**

2019-04-16 09:56

MOT test number

528799967093

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #11

2019-04-16 09:56

MOT test number

224596888143

Result

✗ Failed

- Pass with rectification** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #10

2018-04-09 14:34

MOT test number

149590026556

Result

✓ Passed

**MOT #9**

2017-04-03 16:39

MOT test number

709879605490

Result

✓ Passed

- Advice** Rear Exhaust box outer skin corroded
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Inner Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #8

2016-04-06 16:14

MOT test number

570546456882

Result

✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Rear Tyre tread wearing low on inner edge
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Tyre tread wearing low on inner edge
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #7**

2016-04-06 13:33

MOT test number

553721289398

Result**✗ Failed****Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre tread wearing low on inner edge**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre tread wearing low on inner edge**Fail** Exhaust has a major leak of exhaust gases Centre bracket broken/ corroded causing hole (7.1.2)**MOT #6**

2015-03-27 09:53

MOT test number

455176485041

Result**✓ Passed****Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Passenger seat(s) missing at time of test**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #5** 2015-03-27 09:53**MOT test number** 859266585060**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Passenger seat(s) missing at time of test**MOT #4** 2014-04-17 09:27**MOT test number** 477547104166**Result** ✓ Passed**MOT #3** 2014-04-16 15:54**MOT test number** 555866004180**Result** ✗ Failed**Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)**MOT #2** 2013-03-04 15:55**MOT test number** 698613563056**Result** ✓ Passed



MOT #1	2013-03-04 11:57
MOT test number	438863863096
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
Advice	Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-23
Last registration	2022-10-17
Complete history	See info



Registration #1	2010-03-23	22 mi
Registration #2	2013-03-04	56.560 mi
Registration #3	2013-03-04	56.560 mi
Registration #4	2014-04-16	80.093 mi
Registration #5	2014-04-17	80.093 mi
Registration #6	2015-03-27	103.489 mi
Registration #7	2016-04-06	123.474 mi
Registration #8	2016-04-06	123.474 mi
Registration #9	2017-04-03	137.919 mi
Registration #10	2019-05-20	151.377 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2019-05-20	151.377 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080