





report date: 2024-03-28

## General information

Make	MERCEDES
Model	E E240 ELEGANCE
Colour	Silver
Year of manufacture	2002
Top speed	136 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	170 BHP
	170 5111
Max. torque	240 Nm at 4.500 rpm
Engine capacity	2.397 сс
Cylinders	6
Fuel type	Petrol
Consumption city	16.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.9 mpg
CO2 emission	271 g/km
CO2 label	M



CarCheck.co.uk page 1/20



# Internet history


## Entry 1

Date 2021-12-11

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/20



# MOT history

MOT expiry date	2021-12-29
MOT pass rate	57 %
MOT passed	16
Failed MOT tests	12
Total advice items	81
Total items failed	39

MOT #28		2020-12-30 10:42
MOT test	number	661377832137
Result		✓ Passed
Next expi	ry date	2021-12-29
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Sub-frame pin or bush worn but not resulting in excessive movement (	5.3.4 (a) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Service light on	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/20



**MOT #27** 2020-12-30 10:42

MOT test number 639694936539

Result X Failed

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Service light on

MOT #26 2019-12-20 15:58

**MOT test number** 455904074910

Result \rightarrow Passed

Advice Rear Subframe mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Service light on

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/20



**MOT #25** 2019-12-20 14:10

**MOT test number** 325648737773

Result × Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**DANGEROUS** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Advice Rear Subframe mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

**MAJOR** Front Exhaust system insecure (6.1.2 (a))

**Advice** Service light on

**MOT #24** 2019-01-21 12:35

MOT test number 822774112842

Result 

Passed

**Advice** SERVICE LAMP ON

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/20



MOT #23 2019-01-21 12:35

MOT test number 367617988434

Result × Failed

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice SERVICE LAMP ON

Pass with rectification Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b)

(ii))

**Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Offside Rear fog lamp not working (4.5.1 (a) (ii))

Pass with rectification Offside Headlamp has a product on the lens so that the light output is severely

reduced (4.1.4 (b))

MOT #22 2018-01-30 10:55

MOT test number 376521034874

Result \rightarrow Passed

**Advice** Rear Sub-frame has slight play in a pin/bush (2.4.G.2)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

Advice SERVICE LAMP ON

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice ENG WARNING LAMP ON

CarCheck.co.uk page 6/20



**MOT #21** 2018-01-30 10:55

**MOT test number** 931163937570

Result X Failed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**Advice** SERVICE LAMP ON

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Rear Sub-frame has slight play in a pin/bush (2.4.G.2)

Advice ENG WARNING LAMP ON

**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #20** 2017-01-27 14:50

**MOT test number** 910543301219

**Result** ✓ Passed

**MOT #19** 2017-01-27 11:35

**MOT test number** 658875328598

Result X Failed

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Front wheel bearing has excessive play (2.5.A.3c)

CarCheck.co.uk page 7/20



**MOT #18** 2016-02-01 11:40

**MOT test number** 208435448268

**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #17** 2016-02-01 11:40

**MOT test number** 404548051272

Result X Failed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)

**MOT #16** 2015-01-30 16:30

**MOT test number** 145510135456

Result 

Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 8/20



**MOT #15** 2015-01-30 16:30

**MOT test number** 159300635493

Result × Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)

**Pass with rectification** Offside Front Direction indicator incorrect colour (1.4.A.2f)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Pass with rectification** Nearside Front Direction indicator incorrect colour (1.4.A.2f)

**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)

MOT #14 2014-01-29 13:15

MOT test number 645959524001

Result Passed

**Notice** Outer sills trim covers fitted

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**Notice** Engine covers fitted obscuring some components in the engine bay

Advice Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive

(2.4.A.3)

**Notice** Engine management light on

**Notice** Under-trays fitted obscuring some underside components

**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**Advice** Offside Rear Subframe mounting prescribed area is corroded but not considered excessive

(2.4.A.3)

CarCheck.co.uk page 9/20



MOT #13 2014-01-28 18:03

MOT test number 489188424011

Result × Failed **Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a) **Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)Notice Outer sills trim covers fitted Fail Offside Front position lamp(s) not working (1.1.A.3b) Notice Engine covers fitted obscuring some components in the engine bay Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Rear Rear wheel bearing has excessive play (2.6.2) Advice Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a) Notice Engine management light on Advice Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)Notice Under-trays fitted obscuring some underside components Fail Offside Direction indicator incorrect colour (1.4.A.2f) Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail

CarCheck.co.uk page 10/20



MOT #12 2014-01-24 13:51

MOT test number 107244824453

Result X Failed

**Fail** Offside Headlamp aim too high and too far to the right. (1.8)

**Fail** Offside Rear Sub-frame attachment rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

**Fail** Nearside Headlamp aim too high and too far to the right. (1.8)

**Fail** Nearside Rear Sub-frame attachment rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Notice EML illuminated

**MOT #11** 2013-01-23 13:43

**MOT test number** 727843723069

**Result** ✓ Passed

**MOT #10** 2012-02-01 10:06

MOT test number 326982432030

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 11/20



MOT #9 2012-02-01 10:06

**MOT test number** 528072732060

Result × Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Nearside Headlamp aim too low (1.8)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)

**Pass with rectification** Offside Headlamp aim too low (1.8)

MOT #8 2011-02-01 10:42

**MOT test number** 859202531014

Result 

Passed

**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-01-29 11:14

MOT test number 879199521098

Result × Failed

**Fail** Front coil spring fractured (2.4.C.1a)

**Fail** Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 12/20



MOT test number

Result

Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2010-01-23 08:53 **MOT** test number 133143420047 Result ✓ Passed MOT #4 2009-01-30 09:59 **MOT** test number 832360539038 Result ✓ Passed **MOT** #3 2008-03-05 09:54 **MOT test number** 504455168071 Result ✓ Passed **MOT #2** 2007-02-02 08:58 **MOT test number** 584833537057 Result Passed **Notice** N/side wheel slight play

MOT #1	2006-01-31 16:19
MOT test number	111131336431
Result	<b>✓</b> Passed

CarCheck.co.uk page 13/20



## Tax & MOT check



Tax expired: 18 December 2021

# X MOT

Expired: 29 December 2021

Tax status Expired at 18 December 2021

Days left 862 days too late

MOT expiry date 29 December 2021

Full MOT history See MOT history

## Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 14/20



## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	

#### Damage 2

Damage 2	
Date	
Category	

Type



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 15/20



## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 16/20



# Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloane.	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	Moro info

CarCheck.co.uk page 17/20



## Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 18/20




page 19/20

# Mileage check

CarCheck.co.uk

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-10-21
Last registration	2020-12-30
Complete history	See info



Registration #1	2002-10-21	6 mi
Registration #2	2006-01-31	19.954 mi
Registration #3	2007-02-02	25.252 mi
Registration #4	2008-03-05	30.834 mi
Registration #5	2009-01-30	35.641 mi
Registration #6	2010-01-23	41.200 mi
Registration #7	2011-01-29	45.177 mi
Registration #8	2011-01-29	45.179 mi
Registration #9	2011-02-01	45.203 mi
Registration #10	2012-02-01	49.764 mi
Registration #11	2013-01-23	54.088 mi
Registration #12	2014-01-24	59.090 mi
Registration #13	2014-01-28	59.130 mi
Registration #14	2014-01-29	59.131 mi
Registration #15		11.777 es
Registration #16		
Registration #10		
Registration #17		11.777 es
-		
Registration #17		
Registration #17 Registration #18		
Registration #17 Registration #18 Registration #19		11.777 es 11.777 es 11.777 es
Registration #17 Registration #18 Registration #19 Registration #20		11.777 ea 11.777 ea 11.777 ea
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11.777 ea 11.777 ea 11.777 ea
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23		11.777 est 11.777 est 11.777 est 11.777 est
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24		11.777 est 11.777 est 11.777 est 11.777 est

Registration #27

Registration #28

More info >

mn.n.n



# Additional information

Engine number NOT KNOWN

CarCheck.co.uk page 20/20