



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Grey
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K



Internet history

Entry 1

Date	2021-10-30
Pictures	3
Listing price	View report







source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2023-11-30
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	21
Total items failed	11

MOT #15 2022-11-16 11:24

MOT test number 197746617156

Result ✓ Passed

Next expiry date 2023-11-30

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14 2021-12-01 14:48

MOT test number 227194021323

Result ✓ Passed

MOT #13 2021-10-12 12:16

MOT test number 203134110166

Result ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2021-10-12 11:36**MOT test number** 796984001833**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Reversing lamp inoperative (4.6.1 (a))**MOT #11** 2020-10-19 10:31**MOT test number** 228064489665**Result** ✓ Passed**Advice** Drivers seat has play on electric adjusters but not considered excessive**MOT #10** 2020-10-19 10:31**MOT test number** 343852555574**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Drivers seat has play on electric adjusters but not considered excessive**MOT #9** 2020-10-07 10:08**MOT test number** 785783299914**Result** ✗ Failed**Fail** Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Driver's seat insecure (6.2.5 (a) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2019-04-24 13:53**MOT test number** 579303635685**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust mounting defective middle & rear (6.1.2 (a))**MOT #7** 2018-03-07 15:58**MOT test number** 103247039571**Result** ✓ Passed**MOT #6** 2018-03-07 15:58**MOT test number** 287295554038**Result** ✗ Failed**Pass with rectification** Offside Headlamp cleaning device inoperative (1.7.2)**Pass with rectification** Nearside Headlamp cleaning device inoperative (1.7.2)**MOT #5** 2018-02-27 16:53**MOT test number** 390464464277**Result** ✓ Passed**Advice** Offside Front disc corroded on inner face**MOT #4** 2017-02-16 15:41**MOT test number** 188362902119**Result** ✓ Passed

**MOT #3** 2017-02-16 15:13**MOT test number** 950638181524**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Oil leak**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #2** 2017-02-13 10:03**MOT test number** 657539194928**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Oil leak**MOT #1** 2016-01-05 14:42**MOT test number** 527736044387**Result** ✓ Passed**Advice** Offside door mirror glass cracked



Tax & MOT check

✕
Untaxed

Tax expired:
31 May 2023

✕
MOT

Expired:
30 November 2023

Tax status	Expired at 31 May 2023
Days left	333 days too late
MOT expiry date	30 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LV62WSO
Plate since	2019-03-29
Current registration	 LV62WSO
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-01-20
Last registration	2022-11-16
Complete history	See info



Registration #1	2013-01-20	16 mi
Registration #2	2016-01-05	19.933 mi
Registration #3	2017-02-13	25.142 mi
Registration #4	2017-02-16	25.144 mi
Registration #5	2017-02-16	25.144 mi
Registration #6	2018-02-27	31.191 mi
Registration #7	2018-03-07	31.193 mi
Registration #8	2018-03-07	31.193 mi
Registration #9	2019-04-24	44.043 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K