



VA050RJ

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T200 L SWB P/V
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-16
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-07-29
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	20
Total items failed	38

MOT #20	2021-07-15 14:42
MOT test number	919582377041
Result	✓ Passed
Next expiry date	2022-07-29
Advice	Slight oil leak
Advice	Both outer sill panels light corrosion forming

MOT #19	2020-07-30 16:26
MOT test number	788110985081
Result	✓ Passed

MOT #18	2018-10-20 11:57
MOT test number	121904812323
Result	✓ Passed

**MOT #17**

2018-09-27 16:14

MOT test number

172855379700

Result**✗ Failed**

- Fail** Offside Front Headlamp insecure (4.1.1 (c))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Horn not working (7.7 (a) (ii))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))

MOT #16

2017-10-23 14:40

MOT test number

797895665929

Result**✓ Passed**

- Advice** Offside Rear wheel slight binding
- Advice** Oil leak

**MOT #15**

2017-09-06 16:41

MOT test number

937584829201

Result**✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside rear parking (secondary) brakes imbalanced (3.7.B.6b)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Oil leak
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Body has a sharp edge caused by damage end cap missing (6.1.C.1)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Rear wheel binding

MOT #14

2016-05-03 15:26

MOT test number

905474652826

Result**✓ Passed**

- Advice** Oil leak

**MOT #13** 2015-03-04 14:08**MOT test number** 246913165098**Result** ✓ Passed**Notice** Oil leak**Notice** Front brake discs corroded**Notice** O/s/r brake is binding slightly**MOT #12** 2015-03-03 16:18**MOT test number** 178162565409**Result** ✗ Failed**Fail** Service brake: efficiency below requirements (3.7.B.7)**Notice** O/s/r brake is binding slightly**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** Oil leak**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Front brake discs corroded**MOT #11** 2013-06-10 16:41**MOT test number** 325781663193**Result** ✓ Passed

**MOT #10** 2013-06-10 12:53**MOT test number** 267151663102**Result** ✗ Failed

- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Front Anti-roll bar linkage insecure (2.4.G.1)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2012-05-11 17:56**MOT test number** 346482132108**Result** ✓ Passed**MOT #8** 2012-03-09 17:06**MOT test number** 568129262007**Result** ✗ Failed

- Fail** Emissions not tested (7.0)

MOT #7 2011-03-09 11:57**MOT test number** 848638461086**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2011-03-01 13:51**MOT test number** 125950961053**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front constant velocity joint gaiter split (2.5.C.1a)**Fail** Offside Body has a sharp edge caused by damage (6.1.C.1)**MOT #5** 2010-03-05 14:29**MOT test number** 360044860067**Result** ✓ Passed**Notice** Oil leak on engine , os rear end cap missing on bumper**MOT #4** 2010-03-05 12:47**MOT test number** 101394060079**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Oil leak on engine , os rear end cap missing on bumper**Fail** Nearside Front Headlamp not working on main beam (1.7.5a)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2009-03-04 12:15**MOT test number** 563843169098**Result** ✓ Passed



MOT #2 2009-03-03 14:30

MOT test number 174472369425

Result ✗ Failed

Fail Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

Notice Vehicle has not got van tyres fitted

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1 2008-03-06 12:37

MOT test number 654206668070

Result ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
28 April 2021

✕
MOT

Expired:
29 July 2022

Tax status	Expired at 28 April 2021
Days left	1097 days too late
MOT expiry date	29 July 2022
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-07-28
Last registration	2021-07-15
Complete history	See info



Registration #1	2005-07-28	14 mi
Registration #2	2008-03-06	34.889 mi
Registration #3	2009-03-03	62.629 mi
Registration #4	2009-03-04	62.635 mi
Registration #5	2010-03-05	74.430 mi
Registration #6	2010-03-05	74.434 mi
Registration #7	2011-03-01	90.904 mi
Registration #8	2011-03-09	90.915 mi
Registration #9	2012-03-09	109.739 mi
Registration #10	2012-05-11	109.743 mi
Registration #11	2013-06-10	130.183 mi
Registration #12	2013-06-10	130.183 mi
Registration #13	2013-06-10	130.183 mi
Registration #14	2013-06-10	130.183 mi
Registration #15	2013-06-10	130.183 mi
Registration #16	2013-06-10	130.183 mi
Registration #17	2013-06-10	130.183 mi
Registration #18	2013-06-10	130.183 mi
Registration #19	2013-06-10	130.183 mi
Registration #20	2013-06-10	130.183 mi
Registration #21	2013-06-10	130.183 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1410 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	5M64902