



HYUNDAI

REIHWZB

report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 CRDI COMFORT
Colour	Black
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	260 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg



**MOT history**

<b>MOT #10</b>	2022-10-17 10:44
<b>MOT test number</b>	536198271057
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-10-21

<b>MOT #9</b>	2021-10-15 10:19
<b>MOT test number</b>	499888269502
<b>Result</b>	✓ Passed

**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #8</b>	2020-10-22 10:55
<b>MOT test number</b>	705543564461
<b>Result</b>	✓ Passed

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))

**Minor** Nearside Front Headlamp lens slightly defective Cracked lens (4.1.1 (b) (i))

**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Nearside Rear fog lamp insecure (4.5.1 (c) (i))

**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))

**MOT #7** 2019-04-06 10:05**MOT test number** 570374940865**Result** ✓ Passed**Minor** Nearside Front Lower Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside front tyre worn on inner edge.**MOT #6** 2019-04-06 10:05**MOT test number** 941945850441**Result** ✗ Failed**Advice** Offside front tyre worn on inner edge.**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Lower Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #5** 2018-04-14 11:46**MOT test number** 894069434287**Result** ✓ Passed**Advice** Nearside Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2017-03-28 14:50

**MOT test number**

458823591210

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #3**

2017-03-28 14:50

**MOT test number**

650757823874

**Result**

✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #2**

2016-04-01 10:51

**MOT test number**

123475564470

**Result**

✓ Passed

**MOT #1**

2015-02-17 14:04

**MOT test number**

377468845080

**Result**

✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>RE11WZB</b>
Plate since	2019-09-29
Current registration	<b>RE11WZB</b>
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-07-04
Last registration	2022-10-17
Complete history	<a href="#">See info</a>



Registration #1	2011-07-04	27 mi
Registration #2	2015-02-17	31.779 mi
Registration #3	2016-04-01	39.558 mi
Registration #4	2017-03-28	46.521 mi
Registration #5	2017-03-28	46.521 mi
Registration #6	2018-04-14	54.857 mi
Registration #7	2019-05-20	55.277 mi
Registration #8	2019-05-20	55.277 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2022-10-17	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1565 mm
Length	4475 mm
Wheel base	2700 mm
Kerb weight	1442 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FBBZ335254