



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg
CO2 emission	210 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2024-09-26
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	19
Total items failed	6

MOT #15	2023-09-12 15:07
MOT test number	873737187670
Result	✓ Passed
Next expiry date	2024-09-26

MOT #14	2023-09-12 08:19
MOT test number	688881279728
Result	✗ Failed
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MOT #13	2022-09-26 08:59
MOT test number	848969749534
Result	✓ Passed
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MOT #12** 2021-09-27 12:57**MOT test number** 792770966928**Result** ✓ Passed**Advice** Small chip to windscreen n/s .**Minor** Windscreen damaged but not adversely affecting driver's view large chip (3.2 (a) (i))**MOT #11** 2020-09-21 11:45**MOT test number** 588700760078**Result** ✓ Passed**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Coolant leak RADIATOR**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #10** 2019-10-22 14:44**MOT test number** 512168817980**Result** ✓ Passed**MOT #9** 2019-10-22 13:28**MOT test number** 331228568318**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #8** 2018-10-08 10:20**MOT test number** 604864891918**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**MOT #7** 2018-10-06 10:43**MOT test number** 351524024022**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))**Fail** Brake pad(s) less than 1.5 mm thick both rear (1.1.13 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #6** 2017-10-03 11:27**MOT test number** 118251848370**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #5** 2016-09-28 10:16**MOT test number** 438878924719**Result** ✓ Passed

**MOT #4** 2015-08-07 10:43**MOT test number** 315139715409**Result** ✓ Passed**Notice** Stone chips on front windscreen**MOT #3** 2014-08-01 12:27**MOT test number** 808343414267**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Windscreen stonechipped**MOT #2** 2013-08-09 10:47**MOT test number** 567611223261**Result** ✓ Passed**MOT #1** 2012-08-24 16:37**MOT test number** 475237332226**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
28 April 2024

✓

MOT

Expires:
26 September 2024

Tax status	Expired at 28 April 2024
Days left	2 days too late
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VO09CGG
Plate since	2024-03-29
Current registration	 VO09CGG
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-02
Last registration	2023-09-12
Complete history	See info



Registration #1	2009-03-02	10 mi
Registration #2	2012-08-24	25.588 mi
Registration #3	2013-08-09	32.553 mi
Registration #4	2014-08-01	39.142 mi
Registration #5	2015-08-07	46.022 mi
Registration #6	2016-09-28	50.858 mi
Registration #7	2017-10-03	66.084 mi
Registration #8	2018-10-06	81.808 mi
Registration #9	2018-10-08	81.827 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1230 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	AZJ 766622