





report date: 2024-03-29

## General information

Make	BMW
Model	116 116D M SPORT
Colour	Black
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 сс
Cylinders	3
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



## Internet history

## Entry 1

Date 2021-10-18

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-12-15
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	0

MOT #6	2023-12-14 09:37
MOT test number	618778367548
Result	<b>✓</b> Passed
Next expiry date	2024-12-15
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated ingress of dirt (2.1.3 (g) (i))  Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated ingress of dirt (2.1.3 (g) (i))	l, but preventing the

MOT #5	2023-12-12 10:30
MOT test number	919157746924
Result	<b>×</b> Failed
<b>DANGEROUS</b> Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2	.3 (h))
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but ingress of dirt (2.1.3 (g) (i))	preventing the
MAJOR Brake pad(s) worn down to wear indicator brake pad warning failure on displa	y (1.1.13 (a) (i))
Advice Nearside Front suspect damage to nsf suspension set up, excess camber wea	r
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but ingress of dirt (2.1.3 (g) (i))	t preventing the

CarCheck.co.uk page 3/11



MOT #4 2022-12-16 10:55

**MOT test number** 619386865231

**Result** ✓ Passed

**Advice** Engine covers under trays fitted

MOT #3 2021-11-18 08:48

**MOT test number** 317979318013

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-09-30 10:18

**MOT test number** 528381971761

**Result** ✓ Passed

MOT #1 2020-02-17 13:05

**MOT test number** 254415822256

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	15 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



YK17WPE

report date: 2024-03-29

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>		
***************************************		
***************************************		
	More info >	
Plate changes  See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK W	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



YK17WPE

report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-01
Last registration	2023-12-14
Complete history	See info



Registration #1	2017-03-01	28 mi
Registration #2	2020-02-17	44.518 mi
Registration #3	2020-09-30	47.470 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11




## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1320 kg
Max. allowed weight	1885 kg

## Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 38829631