



PN6IVHW

report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 90
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-07
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	46
Total items failed	9

MOT #18	2024-03-25 14:02
---------	------------------

MOT test number	680031355483
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-24
------------------	------------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and wearing edges (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Lower Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Hand brake high
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2024-03-22 08:38

MOT test number

606167510426

Result**✗ Failed****MAJOR** Central Front Seat belt buckle not functioning as intended (7.1.2 (d))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and wearing edges (5.2.3 (e))**Minor** Offside Lower Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Hand brake high**MOT #16**

2023-03-13 14:17

MOT test number

564464355565

Result**✓ Passed****MOT #15**

2023-03-07 17:48

MOT test number

902563577875

Result**✗ Failed****MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #14** 2022-03-02 15:00**MOT test number** 613679546379**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2022-02-28 10:40**MOT test number** 128745345180**Result** ✗ Failed**MAJOR** Upper Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #12** 2020-12-22 16:36**MOT test number** 191909541216**Result** ✓ Passed**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #11**

2020-12-22 09:01

MOT test number

818573753324

Result**✗ Failed**

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #10

2020-01-17 16:52

MOT test number

337342032858

Result**✓ Passed**

Advice Tyre worn close to legal limit/worn on edge spare wheel (5.2.3 (e))

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear load index for tyre is low (96H)

MOT #9

2020-01-17 15:28

MOT test number

385261543557

Result**✗ Failed**

DANGEROUS Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear load index for tyre is low (96H)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Tyre worn close to legal limit/worn on edge spare wheel (5.2.3 (e))

**MOT #8** 2019-01-15 09:38**MOT test number** 331272941189**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #7** 2018-01-16 12:21**MOT test number** 342695094143**Result** ✓ Passed**MOT #6** 2017-01-09 08:04**MOT test number** 123936869894**Result** ✓ Passed**MOT #5** 2017-01-07 10:20**MOT test number** 807943333820**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #4** 2016-01-08 17:40**MOT test number** 975570796904**Result** ✓ Passed



MOT #3		2016-01-08 17:40
MOT test number		854130229541
Result		✗ Failed
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Offside Front Headlamp not working on dipped beam (1.7.5a)	
Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)	

MOT #2		2014-11-12 12:35
MOT test number		405086414477
Result		✓ Passed

MOT #1		2014-11-12 12:35
MOT test number		147656214301
Result		✗ Failed
Pass with rectification	Nearside Front Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)	



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 June
-------------------	--------------------

Days left	33
------------------	----

MOT expiry date	24 March 2025
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-11-17
Last registration	2024-03-25
Complete history	See info



Registration #1	2011-11-17	26 mi
Registration #2	2014-11-12	82.051 mi
Registration #3	2016-01-08	94.397 mi
Registration #4	2016-01-08	94.397 mi
Registration #5	2017-01-07	110.022 mi
Registration #6	2017-01-09	110.022 mi
Registration #7	2018-01-16	115.919 mi
Registration #8	2019-01-15	124.255 mi
Registration #9	2020-01-17	137.914 mi
Registration #10	2020-01-17	137.916 mi
Registration #11	2020-01-17	137.916 mi
Registration #12	2020-01-17	137.916 mi
Registration #13	2020-01-17	137.916 mi
Registration #14	2020-01-17	137.916 mi
Registration #15	2020-01-17	137.916 mi
Registration #16	2020-01-17	137.916 mi
Registration #17	2020-01-17	137.916 mi
Registration #18	2020-01-17	137.916 mi
Registration #19	2020-01-17	137.916 mi

More info >



Dimensions & weight

Width	2194 mm
Length	4805 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JBBY0050452