





report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER SD ALL4 COOPER SD ALL4
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/12



GK13ZDD

report date: 2024-03-28


Internet history

Entry 3

Date 2021-08-17

Pictures 77

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date	2021-08-03
------	------------


Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

Entry 1

Date	2021-07-23

Pictures 50

Listing price View report









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-25
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	11
Total items failed	2

MOT #12	2023-07-20 09:22
MOT test number	744955874647
Result	✓ Passed
Next expiry date	2024-07-25
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #11		2023-07-20 09:22
MOT test number		221239606856
Result		× Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Rear C	hild Seat fitted not allowing full inspection of adult belt	

MOT #10		2022-07-23 09:59
MOT test r	number	900051841222
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing and offside (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



GK13ZDD

report date: 2024-03-28

MOT #9 2022-07-23 08:35

MOT test number 237672146266

Result X Failed

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Tyre slightly damaged/cracking or perishing BOTH REAR TYRES HAVE LONG CRACKS IN TREAD AND NEARSIDE REAR TYTRE HAS SCREW IN TREAD TOO (5.2.3 (d) (ii))

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #8 2021-07-26 11:27

MOT test number 961882654164

MOT #7 2020-07-03 10:51

MOT test number 817287565304

Result

Passed

MOT #6 2019-07-05 08:21

MOT test number 518757539033

Result

Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2018-06-30 08:48

MOT test number 240410044337

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #4 2017-07-14 11:10

MOT test number 766279503106

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Front Tyre worn close to the legal limit 2mm and worn on inner edge (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #3 2016-07-15 12:49

MOT test number 114336999951

Result ✓ Passed

MOT #2 2016-07-15 09:50

MOT test number 459942113705

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure INNER (4.1.D.1b)

MOT #1 2015-07-23 14:25

MOT test number 488294005220

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	valid until 1 February
Days left	278
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Venicle class	43
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type

Damage 2
Date

Туре



Extra MINI salvage check



Category

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



GK13ZDD

report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners die Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NIE ZIN UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-29
Last registration	2023-07-20
Complete history	See info



Registration #1	2013-03-29	15 mi
Registration #2	2015-07-23	28.508 mi
Registration #3	2016-07-15	36.975 mi
Registration #4	2016-07-15	36.978 mi
Registration #5	2017-07-14	45.789 mi
Registration #6	2018-06-30	52.935 mi
Registration #7	2019-07-05	58.642 mi
Registration #8	2020-07-03	61.744 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		10.777 mg
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1395 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12

Number of axles 2

Engine number 70588556