



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Grey
Year of manufacture	2008
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-01
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-12
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	42
Total items failed	9

MOT #18	2023-12-28 14:14
MOT test number	562425119971
Result	✓ Passed
Next expiry date	2025-01-12
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #17	2023-12-15 16:09
MOT test number	402084135728
Result	✗ Failed
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

**MOT #16** 2023-01-06 14:46**MOT test number** 847234565431**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Front both front tyres worn on edges**MOT #15** 2023-01-06 10:40**MOT test number** 409532721511**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Front both front tyres worn on edges**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2022-01-13 15:01**MOT test number** 618511971483**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2021-12-06 13:44

MOT test number

729846337818

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12

2021-01-19 16:38

MOT test number

239083749281

Result

✓ Passed

- Advice** Vehicle engine cover and under trays fitted unable to fully check some components
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion on edges (1.1.14 (a) (ii))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush slightly split and perished (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Condensation in o/s and n/s front fog lights
- Advice** Nearside Tyre slightly damaged/cracking or perishing age cracking in side wall and tread area (5.2.3 (d) (ii))
- Advice** Rear exhaust heat shield loose

MOT #11

2020-01-02 15:26

MOT test number

773651238721

Result

✓ Passed

- Advice** Slight corrosion in o/s rear coil spring
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Engine cover and under trays fitted
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MOT #10** 2019-01-16 09:02**MOT test number** 685443768715**Result** ✓ Passed**MOT #9** 2019-01-16 09:02**MOT test number** 280657091046**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #8** 2018-01-22 11:39**MOT test number** 625009123015**Result** ✓ Passed**Advice** Engine covers and undersheilds fitted**MOT #7** 2018-01-22 10:25**MOT test number** 756967822941**Result** ✗ Failed**Fail** Nearside Front position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Advice** Engine covers and undersheilds fitted**MOT #6** 2017-02-01 14:43**MOT test number** 932725403326**Result** ✓ Passed**Advice** Undersheilds fitted**Advice** Engine covers fitted

**MOT #5**

2017-01-31 14:18

MOT test number

724216601274

Result

✗ Failed

Fail Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

Advice Undersheilds fitted

Fail Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Engine covers fitted

Fail Central Exhaust has a major leak of exhaust gases (7.1.2)

MOT #4

2016-01-14 12:06

MOT test number

271384903814

Result

✓ Passed

Advice Engine covers and under-trays are fitted which are obscuring some components

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Row 3 seats not in use

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

2015-01-12 10:24

MOT test number

219842115085

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay



MOT #2	2013-02-21 10:58
MOT test number	778972753027
Result	✓ Passed

MOT #1	2011-04-21 09:59
MOT test number	187441411111
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
12 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	12 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-04-22
Last registration	2023-12-28
Complete history	See info



Registration #1	2008-04-22	29 mi
Registration #2	2011-04-21	55.080 mi
Registration #3	2013-02-21	85.990 mi
Registration #4	2015-01-12	102.650 mi
Registration #5	2016-01-14	108.651 mi
Registration #6	2017-01-31	112.271 mi
Registration #7	2017-02-01	112.275 mi
Registration #8	2018-01-22	116.423 mi
Registration #9	2018-01-22	116.423 mi
Registration #10	2019-01-16	121.118 mi
Registration #11	2019-01-16	121.118 mi
Registration #12	2019-01-16	121.118 mi
Registration #13	2019-01-16	121.118 mi
Registration #14	2019-01-16	121.118 mi
Registration #15	2019-01-16	121.118 mi
Registration #16	2019-01-16	121.118 mi
Registration #17	2019-01-16	121.118 mi
Registration #18	2019-01-16	121.118 mi
Registration #19	2019-01-16	121.118 mi
Registration #20	2019-01-16	121.118 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1975 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8D79516