



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D5 SE AWD
Colour	Grey
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-11
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #12 2023-05-04 07:55

MOT test number 947780922136

Result ✓ Passed

Next expiry date 2024-05-11

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11 2022-04-27 14:20

MOT test number 595982043814

Result ✓ Passed

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10 2021-05-12 13:37

MOT test number 102996338528

Result ✓ Passed

**MOT #9** 2021-05-10 14:28**MOT test number** 607944521570**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #8** 2020-02-03 13:33**MOT test number** 103371535598**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-01-16 15:10**MOT test number** 509041156177**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Driver's seat adjustment switch cover missing making fore and aft adjustment difficult**Advice** Front Front windscreen damaged, but affecting driver's view of road. (Chip in zone 'B' less than 40mm)**MOT #6** 2018-02-02 17:28**MOT test number** 224131384790**Result** ✓ Passed**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5** 2017-02-06 15:24**MOT test number** 961852862050**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2016-02-11 09:22**MOT test number** 278850543202**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-02-10 10:19**MOT test number** 977631045039**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-03-07 10:13**MOT test number** 256826564097**Result** ✓ Passed**MOT #1** 2014-03-03 13:31**MOT test number** 987552664039**Result** ✗ Failed**Fail** Offside Front Seat belt locking mechanism does not secure or release (5.2.5a)**Notice** Nail in nearside rear tyre



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
11 May 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	11 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	EY11TLZ
Plate since	2019-09-28
Current registration	EY11TLZ
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-05-18
Last registration	2023-05-04
Complete history	See info



Registration #1	2011-05-18	15 mi
Registration #2	2014-03-03	18.897 mi
Registration #3	2014-03-07	18.926 mi
Registration #4	2015-02-10	24.243 mi
Registration #5	2016-02-11	29.701 mi
Registration #6	2017-02-06	34.965 mi
Registration #7	2018-02-02	39.005 mi
Registration #8	2019-05-20	43.277 mi
Registration #9	2020-05-20	47.549 mi
Registration #10	2021-05-20	51.821 mi
Registration #11	2022-05-20	56.093 mi
Registration #12	2023-05-04	60.365 mi
Registration #13	2024-03-28	64.637 mi
Registration #14	2024-03-28	68.909 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1844 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	961083