





General information

Make	MERCEDES-BENZ
Model	CLS CLS220 BLUETEC AMG LINE
Colour	Grey
Year of manufacture	2015
Top speed	138 mph
0 - 60 mph	8.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	128 g/km
CO2 label	D







Internet history	
Entry 1	
Date	2022-02-14
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-21
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	16
Total items failed	3

MOT #7	2024-03-22 10:45
MOT test number	754083079630
Result	✓ Passed
Next expiry date	2025-03-21
Advice Under trays fitted	
Advice Engine cover fitted	

MOT #6		2023-03-15 11:17
MOT test	number	570763467582
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Engine cover and under trays fitted.	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2022-03-07 13:26
MOT test number	192982454255
Result	✓ Passed





886878514188

MOT #4		2021-04-30 15:53
MOT test	number	911673290244
Result		✓ Passed
Advice	Offside Front Nail in tyre	
Advice	Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))	
MOT #3		2020-05-16 10:06

MOT test number

Result	Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords Wall (5.2.3 (i))	(d)
Fail Nearside Rear Inner Tyre has ply or cords exposed Edge (5.2.3 (d) (ii))	
FailParking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	

MOT #2	2019-05-18 09:14
MOT test number	625066400737
Result	✓ Passed
Advice Offside Rear Nail in tyre	
Advice Nearside Front Tyre wearing thin on Inner and Outer edge	
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))	
Advice Offside Front Inner Tyre has a cut but not deep enough to reach the ply or on inner and outer edge (5.2.3 (d) (i))	cords And wearing thin
Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	





MOT #1	2018-05-22 09:57
MOT test number	379824140848
Result	✓ Passed



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 April 2025	Expires: 21 March 2025
Tax status	Valid until 1 April
Days left	337
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	A PLANE
Туре	
Damage 2	AMPLE
	A A A A A A A A A A A A A A A A A A A
Date	1. E
Category	ant
Туре	

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
formed methods	
Carrent registration	
Pate since	
Farle since Carrent registration	
Faite since Faite since Faite since	1111-21-22





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-05-26
Last registration	2024-03-22
Complete history	See info



Registration #1	2015-05-26	14 mi
Registration #2	2018-05-22	32.054 mi
Registration #3	2019-05-18	40.693 mi
Registration #4	2020-05-16	48.860 mi
Registration #5	2021-04-30	58.090 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	<u>see crash video</u>



Dimensions & weight		
Width	1881 mm	
Height	1418 mm	
Length	4937 mm	
Wheel base	2874 mm	
Kerb weight	1790 kg	
Max. allowed weight	2275 kg	
Additional information		
Fuel tank capacity	59	
Fuel delivery	Direct Injection	
Number of doors	4	
CarCheck.co.uk		page 12/12

Number of seats	4
Number of axles	2
Engine number	65192432757022