



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	TERRACAN CRTD CDX
Colour	Black
Year of manufacture	2004
Top speed	104 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	345 Nm at 2.000 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	38.2 mpg
Consumption combined	32.5 mpg
CO2 emission	222 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-07
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	51
Total items failed	7

MOT #21	2023-08-31 17:20
MOT test number	600837481881
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Fule shield is to rusty.
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Undertry fitted can't check engine.
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #20**

2023-08-31 17:20

MOT test number

756689199785

Result

✗ Failed

- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Fule shield is to rusty.
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Undertry fitted can't check engine.
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #19

2021-09-13 11:27

MOT test number

340577637998

Result

✓ Passed

- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both sides cracks in tread area (5.2.3 (d) (ii))

MOT #18

2020-11-25 09:29

MOT test number

496178902912

Result

✓ Passed

- Advice** Clutch pedal rubber missing
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

**MOT #17** 2019-11-27 08:48**MOT test number** 425291207653**Result** ✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material Before axle brake hose, near fuel tank (1.1.11 (c))

MOT #16 2018-12-05 10:49**MOT test number** 449030477231**Result** ✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake pipe corroded, covered in grease or other material Across axle (1.1.11 (c))

Advice EML light on

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2017-11-08 10:39**MOT test number** 736979255225**Result** ✓ Passed**MOT #14** 2016-11-14 12:05**MOT test number** 347685940712**Result** ✓ Passed

**MOT #13**

2016-11-11 10:19

MOT test number

579100448787

Result**✗ Failed**

- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)
- Fail** Offside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Central Rear high level brakelight not working
- Advice** Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)

MOT #12

2015-12-30 12:03

MOT test number

351530947120

Result**✓ Passed**

- Advice** Brake pipe slightly corroded front to rear brake pipe (3.6.B.2c)
- Advice** Under trays,engine and outer sill covers fitted partial check only
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #11**

2015-12-30 12:03

MOT test number

984684775217

Result**✗ Failed**

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Brake pipe slightly corroded front to rear brake pipe (3.6.B.2c)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Under trays, engine and outer sill covers fitted partial check only
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #10

2014-12-11 10:11

MOT test number

185385244365

Result**✓ Passed**

- Advice** Centre Rear Brake hose slightly deteriorated (3.6.B.4d)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #9** 2013-12-16 09:45**MOT test number** 565150653343**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak on rear diff**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Sill trims fitted, partial examination only**MOT #8** 2013-01-04 09:35**MOT test number** 615354703028**Result** ✓ Passed**Notice** Sill trims fitted, partial examination only**MOT #7** 2012-01-09 11:28**MOT test number** 988869802051**Result** ✓ Passed**MOT #6** 2012-01-09 11:26**MOT test number** 426759002089**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #5** 2011-01-05 10:24**MOT test number** 737785501009**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2010-01-09 12:33
MOT test number	763519700077
Result	✓ Passed
MOT #3	2009-01-06 14:41
MOT test number	663196009002
Result	✓ Passed
MOT #2	2008-12-23 10:59
MOT test number	612298558389
Result	✓ Passed
MOT #1	2007-12-18 17:00
MOT test number	404002357324
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-12-24
Last registration	2023-08-31
Complete history	See info



Registration #1	2004-12-24	26 mi
Registration #2	2007-12-18	25.839 mi
Registration #3	2008-12-23	39.196 mi
Registration #4	2009-01-06	33.378 mi
Registration #5	2010-01-09	41.848 mi
Registration #6	2011-01-05	48.265 mi
Registration #7	2012-01-09	54.240 mi
Registration #8	2012-01-09	54.240 mi
Registration #9	2013-01-04	64.053 mi
Registration #10	2013-12-16	73.813 mi
Registration #11	2014-12-11	82.011 mi
Registration #12	2015-12-30	91.161 mi
Registration #13	2016-01-01	91.161 mi
Registration #14	2016-01-01	91.161 mi
Registration #15	2016-01-01	91.161 mi
Registration #16	2016-01-01	91.161 mi
Registration #17	2016-01-01	91.161 mi
Registration #18	2016-01-01	91.161 mi
Registration #19	2016-01-01	91.161 mi
Registration #20	2016-01-01	91.161 mi
Registration #21	2016-01-01	91.161 mi
Registration #22	2016-01-01	91.161 mi
Registration #23	2016-01-01	91.161 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1840 mm
Length	4700 mm
Wheel base	2750 mm
Kerb weight	2265 kg
Max. allowed weight	2620 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	J3874184