



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Blue
Year of manufacture	2004
Top speed	100 mph
0 - 60 mph	14.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	164 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-12-20
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-24
MOT pass rate	69 %
MOT passed	18
Failed MOT tests	8
Total advice items	66
Total items failed	10

MOT #26 2024-04-25 10:00

MOT test number 756122577361

Result ✓ Passed

Next expiry date 2025-04-24

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** SLIGHT BLOW EXHAUST
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #25 2023-01-11 15:16

MOT test number 668732473842

Result ✓ Passed

- Advice** Both front tyres worn on inner edges
- Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear chassis area corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #24**

2023-01-09 13:04

MOT test number

546781326486

Result**✗ Failed****MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Both front tyres worn on inner edges**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear chassis area corroded**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #23**

2022-01-14 11:19

MOT test number

447065200192

Result**✓ Passed****MOT #22**

2022-01-06 12:03

MOT test number

995783386938

Result**✗ Failed****MAJOR** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Offside Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))**MAJOR** Front Registration plate inscription illegible (0.1 (b))**MAJOR** Nearside Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))

**MOT #21**

2021-06-01 10:47

MOT test number

645791684398

Result

✓ Passed

- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #20

2020-06-11 09:55

MOT test number

326350539941

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #19

2020-06-10 08:54

MOT test number

635416817825

Result

✗ Failed

- MAJOR** Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Emissions not tested (8.2.1.2 (d))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #18**

2019-05-13 13:02

MOT test number

663376102716

Result

✓ Passed

- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #17

2019-05-13 13:02

MOT test number

595071801796

Result

✗ Failed

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #16

2018-04-23 09:49

MOT test number

774903444710

Result

✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded Axle brake pipe. (3.6.B.2c)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Rear Brake pipe slightly corroded axle brake pipe. (3.6.B.2c)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #15**

2017-05-17 08:56

MOT test number

717129026243

Result

✓ Passed

Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #14**

2017-05-17 08:56

MOT test number

672192367072

Result

✗ Failed

Advice Offside Rear Nail in tyre**Pass with rectification** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Pass with rectification** Rear fog lamp not working (1.3.2b)**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #13**

2016-05-18 08:14

MOT test number

906882655298

Result

✓ Passed

**MOT #12** 2016-05-16 10:33**MOT test number** 370722730108**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**MOT #11** 2015-05-14 15:25**MOT test number** 219464135162**Result** ✓ Passed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #10** 2015-05-14 10:50**MOT test number** 215544035191**Result** ✗ Failed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #9** 2014-05-15 12:14**MOT test number** 939355334161**Result** ✓ Passed**MOT #8** 2013-04-19 10:42**MOT test number** 295569103176**Result** ✓ Passed**MOT #7** 2012-04-17 10:04**MOT test number** 907038302152**Result** ✓ Passed

**MOT #6** 2011-04-12 10:47**MOT test number** 368972501193**Result** ✓ Passed**MOT #5** 2010-04-19 09:47**MOT test number** 904399300128**Result** ✓ Passed**MOT #4** 2009-04-29 16:38**MOT test number** 270579519492**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2009-04-27 15:38**MOT test number** 551157119106**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear fog lamp tell tale not working (1.3.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2008-04-14 15:00**MOT test number** 270995008105**Result** ✓ Passed



MOT #1	2007-04-25 10:05
MOT test number	554055217163
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
24 April 2025

Tax status	Expired at 1 April 2024
Days left	27 days too late
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	K300LGA
Plate since	2019-03-28
Current registration	K300LGA
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-06-08
Last registration	2024-04-25
Complete history	See info



Registration #1	2004-06-08	20 mi
Registration #2	2007-04-25	14.282 mi
Registration #3	2008-04-14	19.465 mi
Registration #4	2009-04-27	22.785 mi
Registration #5	2009-04-29	22.789 mi
Registration #6	2010-04-19	26.416 mi
Registration #7	2011-04-12	29.170 mi
Registration #8	2012-04-17	31.530 mi
Registration #9	2013-04-19	33.348 mi
Registration #10	2014-05-15	35.054 mi
Registration #11	2015-05-14	36.824 mi
Registration #12	2015-05-14	36.824 mi
Registration #13	2016-05-16	38.094 mi
Registration #14	2016-05-18	38.102 mi
Registration #15	2016-05-18	38.102 mi
Registration #16	2016-05-18	38.102 mi
Registration #17	2016-05-18	38.102 mi
Registration #18	2016-05-18	38.102 mi
Registration #19	2016-05-18	38.102 mi
Registration #20	2016-05-18	38.102 mi
Registration #21	2016-05-18	38.102 mi
Registration #22	2016-05-18	38.102 mi
Registration #23	2016-05-18	38.102 mi
Registration #24	2016-05-18	38.102 mi
Registration #25	2016-05-18	38.102 mi
Registration #26	2016-05-18	38.102 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

[More info >](#)



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1102 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	64EA4634170