





report date: 2024-03-29

#### General information

Make	TOYOTA
Model	PRIUS VVT-I BUSINESS EDITION
Colour	Blue
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	10.6 seconds
Gearbox	1 speed CVT

#### Engine & fuel consumption

Power	121 BHP
Max. torque	305 Nm at 3.600 rpm
<b>Engine capacity</b>	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	94.0 mpg
CO2 emission	70 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history


#### Entry 1

Date 2021-10-01

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2025-04-02
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	11
Total items failed	1

MOT #13		2024-04-03 12:35
MOT test	number	820782481046
Result		✓ Passed
Next expi	ry date	2025-04-02
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

MOT #12		2023-10-06 15:02
MOT test nu	mber	847116124675
Result		✓ Passed
MOT #11		2023-03-29 13:09
MOT test nu	mber	228255948685
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Nail in tyre	

MOT #10	2022-10-05 13:33
MOT test number	332763745044
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2022-10-01 14:28

**MOT test number** 645385261543

Result X Failed

Advice Nearside Steering linkage ball joint has slight play tierod (2.1.3 (b) (i))

MAJOR Offside Steering linkage ball joint has excessive play tierod (2.1.3 (b) (i))

MAJOR Steering column attachment defective strong noice when turning the steering wheel (2.2.2 (d) (i))

MOT #8 2022-03-12 16:32

**MOT test number** 859881619892

**Result** ✓ Passed

MOT #7 2022-03-11 14:05

**MOT test number** 191729855957

**Result** X Failed

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Windscreen wiper not working only working on one speed and stopping at random places (3.4 (a))

Minor Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

MAJOR Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #6 2021-10-01 14:38

**MOT test number** 818322197030

**Result** ✓ Passed

MOT #5 2020-12-07 15:52

**MOT test number** 654779071226

**Result** ✓ Passed

CarCheck.co.uk page 4/12



MOT #2

OU16MXE report date: 2024-03-29

2019-06-06 12:16

 MOT #4
 2019-12-06 11:16

 MOT test number
 822288480077

 Result
 ✓ Passed

 MOT #3
 2019-12-06 11:16

 MOT test number
 538794103116

 Result
 X Failed

 Pass with rectification
 Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT test number	32/535994988
Result	<b>✓</b> Passed
MOT #1	2018-12-06 12:33
MOT test number	713727965023
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	2 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

A	la francia de la composición de la comp
Owner	nistory

Owner mistory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
THE STATE OF THE S	
***************************************	
************	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	OK STATE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2016-07-21
Last registration	2024-04-03
Complete history	See info



Registration #1	2016-07-21	27 mi
Registration #2	2018-12-06	31.728 mi
Registration #3	2019-06-06	46.434 mi
Registration #4	2019-12-06	71.384 mi
Registration #5	2019-12-06	71.384 mi
Registration #6	2020-12-07	100.614 mi
Registration #7	2021-10-01	108.521 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		71,777 ms

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	92%
Children	82%
Pedestrian	77%
Safety systems	85%
Overall rating	85%
Video	see crash video



## Dimensions & weight

Width	1760 mm
Height	1470 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1375 kg
Max. allowed weight	1790 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 2ZR6850033