






report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-VTEC ES GT
Colour	Silver
Year of manufacture	2015
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 3

Date 2022-10-15

Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 2

Date 2022-05-04

Pictures 56

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2022-01-04
Pictures	0

Listing price <u>View report</u>

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT histo	orv
-----------	-----

MOT expiry date	2025-01-15
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #9	2024-01-02 09:15
MOT test number	360784499664
Result	✓ Passed
Next expiry date	2025-01-15

MOT #8	2023-01-16 14:19
MOT test number	721489272794
Result	✓ Passed

MOT #7	2022-07-01 13:33
MOT test number	232120137393
Result	✓ Passed

MOT #6	2022-03-15 12:32
MOT test number	100156946602
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Rear tyres have uneven tread wear and cracking in between treads

Advice Both front track rod end gaiters perishing

Advice Front tyres worn on edges

MOT #4 2021-02-08 14:11 **MOT** test number 380615122004 Result ✓ Passed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii)) Advice Towball/hitch not fitted at time of test Advice Offside track rod end dust cover cracking Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii)) **Advice** Headlamp aims tested as presented, level switch position 3

MOT #3	2020-02-06 11:19
MOT test number	758298291227
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing in tread (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing in tread (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/12



AU15XNN report date: 2024-03-29

MOT #2 2019-02-28 15:02

MOT test number 705738867678

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing Perishing and cracking and wearing unevenly on inner edge (5.2.3 (d) (ii))

Advice Items removed from driver's view prior to test Camera

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perishing and cracking and wearing unevenly on inner edge (5.2.3 (d) (ii))

MOT #1 2018-02-28 10:08

MOT test number 135921632655

Result ✓ Passed

CarCheck.co.uk page 5/12



AU15XNN report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



AU15XNN report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



larine scinces

Plate since

AU15XNN

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this HONDA? How many owners did this HON have? Check it in the premium report and see all owner registrations. Download the full report here .	DΑ

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

THE STATE OF THE S	
More info	>
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	

More info >

EXCESS

CarCheck.co.uk page 9/12



AU15XNN report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-02
Last registration	2024-01-02
Complete history	See info



Registration #1	2015-03-02	6 mi
Registration #2	2018-02-28	15.949 mi
Registration #3	2019-02-28	23.623 mi
Registration #4	2020-02-06	27.208 mi
Registration #5	2021-02-08	29.975 mi
Registration #6	2021-11-18	34.626 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		11.777 mg

More info >

CarCheck.co.uk page 11/12



AU15XNN report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1501 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	R20A35050020

CarCheck.co.uk page 12/12