



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE NAV BLUE DRIVE
Colour	Silver
Year of manufacture	2015
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-22
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-04
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	18
Total items failed	12

MOT #10	2023-10-03 13:12
MOT test number	393291158971
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))
Advice	Play in steering rack inner joint(s)
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2023-10-02 16:06**MOT test number** 665479301973**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))**MOT #8** 2022-10-05 14:28**MOT test number** 786214358545**Result** ✓ Passed

**MOT #7** 2022-10-01 11:58**MOT test number** 359460428447**Result** ✗ Failed**Fail** Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Nearside Front Lower Steering linkage ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear low efficiency**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #6** 2021-10-04 12:36**MOT test number** 420907186393**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened o/s n/s (1.1.14 (a) (ii))**MOT #5** 2021-08-19 13:56**MOT test number** 493401940103**Result** ✓ Passed

**MOT #4** 2021-08-18 10:05**MOT test number** 744738411625**Result** ✗ Failed

- Fail** Offside Rear Suspension arm pin or bush excessively worn front of arm (5.3.4 (a) (i))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn front of arm (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

MOT #3 2020-08-21 13:15**MOT test number** 911619270602**Result** ✓ Passed**MOT #2** 2019-08-14 09:05**MOT test number** 377986674566**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened discs (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened discs (1.1.14 (a) (ii))

MOT #1 2018-08-24 11:43**MOT test number** 847295397822**Result** ✓ Passed

- Advice** Diesel emissions too low for smoke meter to detect



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-01
Last registration	2023-10-03
Complete history	See info



Registration #1	2015-09-01	17 mi
Registration #2	2018-08-24	77.068 mi
Registration #3	2019-08-14	105.274 mi
Registration #4	2020-08-21	127.941 mi
Registration #5	2021-08-18	146.744 mi
Registration #6	2021-08-19	146.744 mi
Registration #7	2023-10-03	146.744 mi
Registration #8	2023-10-03	146.744 mi
Registration #9	2023-10-03	146.744 mi
Registration #10	2023-10-03	146.744 mi
Registration #11	2023-10-03	146.744 mi
Registration #12	2023-10-03	146.744 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDFZ388234