



DUIOPVY

report date: 2024-03-28

General information

Make	NISSAN
Model	PRIMASTAR DCI SE SHR P/V
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-27
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-11
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	33
Total items failed	28

MOT #21	2023-06-12 16:01
MOT test number	354220360320
Result	✓ Passed
Next expiry date	2024-06-11

MOT #20	2023-06-02 13:50
MOT test number	934175826593
Result	✗ Failed
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #19	2022-05-25 08:43
MOT test number	367713700978
Result	✓ Passed
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #18**

2022-05-25 08:43

**MOT test number**

691245457649

**Result**

✗ Failed

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #17**

2021-06-04 07:27

**MOT test number**

364562564928

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated small hole (6.1.7 (g) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Rear Brake hose slightly twisted (1.1.12 (b) (i))**MOT #16**

2021-06-02 12:56

**MOT test number**

281113078733

**Result**

✗ Failed

**Fail** Nearside Front Macpherson strut pin or bush excessively worn top mount (5.3.4 (a) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated small hole (6.1.7 (g) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Rear Brake hose slightly twisted (1.1.12 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))



MOT #15	2020-06-06 10:03
MOT test number	709935160033
Result	✓ Passed
Advice	Nearside Front fog light not working

MOT #14	2020-06-01 09:04
MOT test number	600288485397
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Position lamp not working both front (4.2.1 (a) (ii))
Fail	Brake pedal has insufficient reserve travel creeps to floor (1.1.2 (a))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Offside Rear Suspension arm pin or bush excessively worn axle bush (5.3.4 (a) (i))
Advice	Nearside Front fog light not working

MOT #13	2019-10-21 13:32
MOT test number	379439591509
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Upper Engine mounting damaged but not to excess (6.1.8 (a) (i))
Advice	Nearside Front fog light not working
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2019-10-21 08:20

**MOT test number**

213578279002

**Result****✗ Failed****Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front fog light not working**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Offside Upper Engine mounting damaged but not to excess (6.1.8 (a) (i))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #11**

2018-10-19 12:34

**MOT test number**

806260245876

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front tyres worn on edges

**MOT #10**

2018-10-19 06:42

**MOT test number**

105114060354

**Result**

✗ Failed

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Front tyres worn on edges**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Rear Seat belt not functioning as intended (7.1.2 (c))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #9**

2017-10-24 09:36

**MOT test number**

385092768781

**Result**

✓ Passed

**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #8**

2016-10-28 08:06

**MOT test number**

154442956420

**Result**

✓ Passed

**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Oil leak**MOT #7**

2015-09-02 15:35

**MOT test number**

234568940706

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-09-02 15:35**MOT test number** 783003753864**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2014-09-03 12:53**MOT test number** 509486344287**Result** ✓ Passed**MOT #4** 2014-03-07 17:21**MOT test number** 277896364062**Result** ✓ Passed**MOT #3** 2014-03-07 15:58**MOT test number** 486846864097**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2013-02-20 15:39**MOT test number** 158311453069**Result** ✓ Passed





MOT #1	2013-02-08 16:06
MOT test number	798389633086
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Stop lamp not working (1.2.1b)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
11 June 2024

Tax status		Valid until 1 June
Days left		33
MOT expiry date		11 June 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>DU10PVY</b>
Plate since	2019-09-28
Current registration	<b>DU10PVY</b>
Plate since	2019-09-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2010-03-02
Last registration	2023-06-12
Complete history	<a href="#">See info</a>



Registration #1	2010-03-02	25 mi
Registration #2	2013-02-08	62.957 mi
Registration #3	2013-02-20	63.685 mi
Registration #4	2014-03-07	88.276 mi
Registration #5	2014-03-07	88.279 mi
Registration #6	2014-09-03	93.537 mi
Registration #7	2015-09-02	111.956 mi
Registration #8	2015-09-02	111.956 mi
Registration #9	2016-10-28	144.434 mi
Registration #10	2017-10-24	161.756 mi
Registration #11	2018-10-19	178.302 mi
Registration #12	2018-10-19	178.312 mi
Registration #13	2019-06-20	201.277 mi
Registration #14	2019-06-20	201.277 mi
Registration #15	2019-06-20	201.277 mi
Registration #16	2019-06-20	201.277 mi
Registration #17	2019-06-20	201.277 mi
Registration #18	2019-06-20	201.277 mi
Registration #19	2019-06-20	201.277 mi
Registration #20	2019-06-20	201.277 mi
Registration #21	2019-06-20	201.277 mi
Registration #22	2019-06-20	201.277 mi
Registration #23	2019-06-20	201.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	072560