



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Black
Year of manufacture	2009
Top speed	128 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	148 g/km
CO2 label	F






Internet history

Entry 1


Date	2021-08-06
Pictures	16
Listing price	View report




Click & Collect


Start your deal online or by phone.
When you visit, our safe and clean environment has been designed for a contactless viewing and handover with you.

Visit our website for more info



With the outbreak of COVID-19 and the restrictions that are being put in place to prevent the spread of infection within public venues, and the wishes of some people wanting to implement social distancing, the team at Lakeview Cars just wanted to reassure you that we have implemented measures, in order to continue with offering you our unrivalled customer service.






Click & Deliver

Complete your deal online or by phone.
Then arrange for the sanitised vehicle to be delivered to you.


Visit our website for more info



You can contact us at Lakeview Cars on any of the following methods where one of our Team will come back to you ASAP:

- Call us on 01767 316473
- 'WhatsApp' us on 07507 128021
- Use our 'Click & Reserve' facility on our website
- Use our 'Live Chat' facility on our website
- Complete an online enquiry on our website
- Send us an email on lakeviewcars@yahoo.co.uk

We wish you good health and support in keeping one another safe.



source: autotrader.co.uk



MOT history

MOT expiry date	2023-11-14
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	48
Total items failed	2

MOT #18	2022-11-15 13:49
MOT test number	181655761682
Result	✓ Passed
Next expiry date	2023-11-14

MOT #17	2022-11-08 10:04
MOT test number	766816177434
Result	✗ Failed
MAJOR	Electronic stability control warning lamp indicates a fault (7.12 (e))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
MAJOR	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #16	2021-11-12 11:31
MOT test number	159791101738
Result	✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear tyre worn

**MOT #15**

2021-11-10 17:47

MOT test number

420197322192

Result**✗ Failed****DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear tyre worn**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #14**

2021-08-12 16:17

MOT test number

325371397130

Result**✗ Failed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 235/45R17 (5.2.3 (e))**MAJOR** Offside Rear Tyre(s) of different sizes are fitted on the same axle. tyre tread also low tread (5.2.3 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Macpherson strut top bush or bearing has excessive wear or free play Top mount collapsed (5.3.4 (a) (i))**Advice** Glow plug light flashing**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm 235/45R17 (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #13** 2020-08-19 16:12**MOT test number** 338395946967**Result** ✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2020-08-06 11:32**MOT test number** 386372370810**Result** ✗ Failed

- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #11 2019-08-01 11:04**MOT test number** 217103971210**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2019-07-30 12:50

MOT test number

978348706772

Result**✗ Failed****MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Side repeater flashing more than 120 times a minute (4.4.4 (a))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9**

2018-08-02 11:04

MOT test number

108740759168

Result**✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #8**

2018-08-01 11:49

MOT test number

866884001164

Result**✗ Failed****MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (5.2.3 (d) (i))**MAJOR** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**MOT #7** 2017-08-04 10:07**MOT test number** 893386005006**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #6** 2016-08-02 10:37**MOT test number** 307683036970**Result** ✓ Passed**MOT #5** 2015-07-21 10:55**MOT test number** 395622305290**Result** ✓ Passed**MOT #4** 2014-08-02 11:30**MOT test number** 997944114288**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-08-01 14:12**MOT test number** 826493813286**Result** ✓ Passed**MOT #2** 2012-08-01 11:10**MOT test number** 136394012216**Result** ✓ Passed



MOT #1	2012-08-01 11:10
MOT test number	738464412274
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VN09FLF
Plate since	2019-09-29
Current registration	 VN09FLF
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-06-29
Last registration	2022-11-15
Complete history	See info



Registration #1	2009-06-29	22 mi
Registration #2	2012-08-01	76.903 mi
Registration #3	2013-08-01	84.665 mi
Registration #4	2014-08-02	91.991 mi
Registration #5	2015-07-21	100.971 mi
Registration #6	2016-08-02	108.166 mi
Registration #7	2017-08-04	113.967 mi
Registration #8	2018-08-01	118.108 mi
Registration #9	2018-08-02	118.118 mi
Registration #10	2019-07-30	124.649 mi
Registration #11	2019-08-01	124.649 mi
Registration #12	2019-08-01	124.649 mi
Registration #13	2019-08-01	124.649 mi
Registration #14	2019-08-01	124.649 mi
Registration #15	2019-08-01	124.649 mi
Registration #16	2019-08-01	124.649 mi
Registration #17	2019-08-01	124.649 mi
Registration #18	2019-08-01	124.649 mi
Registration #19	2019-08-01	124.649 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 174034