



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	JETTA SPORT TDI
Colour	Silver
Year of manufacture	2006
Top speed	128 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-29
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-17
MOT pass rate	58 %
MOT passed	14
Failed MOT tests	10
Total advice items	66
Total items failed	20

MOT #24	2024-03-25 10:54
MOT test number	559723849228
Result	✓ Passed
Next expiry date	2025-04-17

MOT #23	2023-04-18 13:13
MOT test number	457252651728
Result	✓ Passed
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #22	2023-04-18 13:13
MOT test number	424294387957
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid split at bonnet hinge (3.5 (a))
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #21**

2023-02-02 09:51

MOT test number

701396060433

Result**✗ Failed****DANGEROUS** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))**MAJOR** Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))**MAJOR** Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #20**

2022-02-03 08:27

MOT test number

562933138448

Result**✓ Passed****Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge on limit - change asap (5.2.3 (e))**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2022-01-25 08:55

MOT test number

854548290319

Result**✗ Failed**

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge on limit - change asap (5.2.3 (e))
- MAJOR** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall damaged (5.2.3 (d) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #18

2021-01-21 16:30

MOT test number

573291787979

Result**✓ Passed**

- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #17**

2021-01-20 10:47

MOT test number

408570279385

Result**✗ Failed**

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MAJOR Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #16

2019-07-22 12:41

MOT test number

670222674064

Result**✓ Passed****MOT #15**

2019-07-22 07:49

MOT test number

225563454811

Result**✗ Failed**

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #14

2018-07-10 07:41

MOT test number

880490217919

Result**✓ Passed**

**MOT #13**

2017-07-19 13:14

MOT test number

540384646495

Result

✓ Passed

Advice

Offside Rear Tyre worn close to the legal limit worn inner edge (4.1.E.1)

MOT #12

2017-07-19 13:14

MOT test number

596881849291

Result

✗ Failed

Pass with rectification

Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Pass with rectification

Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice

Offside Rear Tyre worn close to the legal limit worn inner edge (4.1.E.1)

Pass with rectification

Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Pass with rectification

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification

Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #11

2016-06-28 08:53

MOT test number

513913704890

Result

✓ Passed

Advice

Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice

Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt Both front upper (2.4.G.2)

MOT #10

2015-07-20 15:42

MOT test number

246891905208

Result

✓ Passed

**MOT #9** 2015-07-17 12:14**MOT test number** 758848195120**Result** ✗ Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Rear coil spring broken (2.4.C.1a)

Notice Oil leak

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Notice Nail in offside rear tyre

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2014-07-22 12:39**MOT test number** 255733504266**Result** ✓ Passed

**MOT #7** 2013-07-25 17:27**MOT test number** 116226603230**Result** ✓ Passed**Notice** Both front seat belts been stiched over at bottom**Notice** Off side rear coil spring rusty**MOT #6** 2013-07-25 13:53**MOT test number** 826876003240**Result** ✗ Failed**Notice** Both front seat belts been stiched over at bottom**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Off side rear coil spring rusty**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #5** 2012-01-04 13:22**MOT test number** 695784402014**Result** ✓ Passed**MOT #4** 2012-01-03 14:51**MOT test number** 125753102004**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3** 2010-12-29 14:56**MOT test number** 280643060359**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Nail in offside front tyre**MOT #2** 2009-12-22 09:54**MOT test number** 890556359392**Result** ✓ Passed**Notice** Nearside rear tyre has a screw in it**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front number plate is slightly deteriorated**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-12-22 09:54**MOT test number** 993536459393**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front number plate is slightly deteriorated**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre has a screw in it**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
17 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL56EYG
Plate since	2024-03-28
Current registration	 GL56EYG
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-12-29
Last registration	2024-03-25
Complete history	See info



Registration #1	2006-12-29	22 mi
Registration #2	2009-12-22	21.674 mi
Registration #3	2010-12-29	27.770 mi
Registration #4	2012-01-03	37.167 mi
Registration #5	2012-01-04	37.174 mi
Registration #6	2013-07-25	52.999 mi
Registration #7	2013-07-25	52.999 mi
Registration #8	2014-07-22	61.755 mi
Registration #9	2015-07-17	73.355 mi
Registration #10	2015-07-20	73.385 mi
Registration #11	2016-06-28	81.666 mi
Registration #12	2017-07-19	91.903 mi
Registration #13	2017-07-19	91.903 mi
Registration #14	2018-06-28	91.903 mi
Registration #15	2019-06-28	91.903 mi
Registration #16	2020-06-28	91.903 mi
Registration #17	2021-06-28	91.903 mi
Registration #18	2022-06-28	91.903 mi
Registration #19	2023-06-28	91.903 mi
Registration #20	2024-03-25	91.903 mi
Registration #21	2024-03-25	91.903 mi
Registration #22	2024-03-25	91.903 mi
Registration #23	2024-03-25	91.903 mi
Registration #24	2024-03-25	91.903 mi
Registration #25	2024-03-25	91.903 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1556 kg
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BKD 482872