



VN59BGE

report date: 2024-03-28

General information

Make	MAZDA
Model	3 D SE AC
Colour	Silver
Year of manufacture	-
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #13</b>	2020-08-24 09:03
<b>MOT test number</b>	172059719054
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-09-16

<b>MOT #12</b>	2019-09-05 12:15
<b>MOT test number</b>	385691337250
<b>Result</b>	✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Under tray fitted
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Noise from hub when rotated
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Engine cover fitted
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Vehicle underside covered in under seal

**MOT #11**

2018-08-17 10:54

**MOT test number**

855366801387

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Under side of vehicle covered in under seal
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine cover/under trays fitted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10**

2017-08-22 13:02

**MOT test number**

125247487059

**Result**

✓ Passed

- Advice** Engine cover fitted
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has been repaired at centre section
- Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Under trays fitted
- Advice** Oil leak Engine
- Advice** Rear registration plate faded but not likely to be misread (6.3.1d)

**MOT #9**

2017-08-21 08:52

**MOT test number**

657878224997

**Result****✗ Failed**

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Items removed from driver's view prior to test Rear view mirror

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Engine cover fitted

**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)

**Advice** Exhaust has been repaired at centre section

**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Oil leak Engine

**Advice** Front Play in steering rack inner joint(s)

**Advice** Under trays fitted

**MOT #8**

2016-08-17 07:47

**MOT test number**

335700450690

**Result****✓ Passed**

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)



<b>MOT #7</b>	2015-08-22 14:19
<b>MOT test number</b>	603283485007
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Tyre worn close to the legal limit both rear (4.1.E.1)

<b>MOT #6</b>	2015-08-18 00:00
<b>MOT test number</b>	227604477155
<b>Result</b>	✗ Failed
<b>Advice</b>	Rear Tyre worn close to the legal limit both (4.1.E.1)
<b>Fail</b>	Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement bush (2.4.G.2)
<b>Fail</b>	Nearside Rear Suspension arm rubber bush deteriorated resulting in excessive movement bush (2.4.G.2)

<b>MOT #5</b>	2015-08-18 00:00
<b>MOT test number</b>	811759648821
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Suspension arm rubber mounting bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)
<b>Fail</b>	Nearside Front Suspension arm rubber mounting bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)
<b>Advice</b>	Rear Tyre worn close to the legal limit both rear (4.1.E.1)

<b>MOT #4</b>	2014-08-23 11:23
<b>MOT test number</b>	659675334273
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2014-08-23 10:22
<b>MOT test number</b>	819425034288
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2013-09-17 17:01
MOT test number	437210863202
Result	✓ Passed

MOT #1	2013-01-15 16:15
MOT test number	105705213035
Result	✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Child seats fitted at offside rear and nearside rear
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Emissions too clean to register on smoke meter



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-11-20
Last registration	2020-08-24
Complete history	<a href="#">See info</a>



Registration #1	2009-11-20	13 mi
Registration #2	2013-01-15	42.616 mi
Registration #3	2013-09-17	46.224 mi
Registration #4	2014-08-23	54.207 mi
Registration #5	2014-08-23	54.207 mi
Registration #6	2015-08-18	59.974 mi
Registration #7	2015-08-22	60.035 mi
Registration #8	2015-08-22	60.035 mi
Registration #9	2015-08-22	60.035 mi
Registration #10	2015-08-22	60.035 mi
Registration #11	2015-08-22	60.035 mi
Registration #12	2015-08-22	60.035 mi
Registration #13	2015-08-22	60.035 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4415 mm
Max. allowed weight	1825 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	Y6 294254