



report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | LEXUS |
| Model | IS 300H F SPORT |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 125 mph |
| Gearbox | 1 speed CVT |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 220 BHP |
| Max. torque | 221 Nm at 4.200 rpm |
| Engine capacity | 2.494 cc |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 109 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-11-03 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-14 |
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 1 |

| | |
|------------------|---|
| MOT #8 | 2023-09-12 14:14 |
| MOT test number | 194638643626 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-14 |
| Advice | Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) |

| | |
|-----------------|---|
| MOT #7 | 2023-09-11 11:02 |
| MOT test number | 530085683543 |
| Result | ✗ Failed |
| Fail | Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm both sides (5.2.3 (e)) |
| Advice | Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) |
| Advice | Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #6 | 2022-09-15 14:51 |
| MOT test number | 475219053947 |
| Result | ✓ Passed |
| Advice | Front Inner Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #5 | 2021-10-14 09:38 |
| MOT test number | 185566036020 |
| Result | ✓ Passed |



| | |
|------------------------|---|
| MOT #4 | 2020-10-14 10:41 |
| MOT test number | 255123434380 |
| Result | ✓ Passed |
| Advice | Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|------------------------|------------------|
| MOT #3 | 2019-10-15 13:23 |
| MOT test number | 843052613424 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #2 | 2018-09-24 16:29 |
| MOT test number | 288580468003 |
| Result | ✓ Passed |

| | |
|------------------------|--|
| MOT #1 | 2017-10-16 15:17 |
| MOT test number | 989325638195 |
| Result | ✓ Passed |
| Advice | Both rear tyres inner edges close to limit of wear |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
14 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 14 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 59 |
| Band | B |
| Single payment (12 months) | £ 10,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 10,50,- |



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this LEXUS had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | HF64WYR |
| Plate since | 2019-09-29 |
| Current registration | HF64WYR |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2014-10-17 |
| Last registration | 2023-09-12 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-10-17 | 7 mi |
| Registration #2 | 2017-10-16 | 36.936 mi |
| Registration #3 | 2018-09-24 | 45.578 mi |
| Registration #4 | 2019-10-15 | 55.053 mi |
| Registration #5 | 2020-10-14 | 64.473 mi |
| Registration #6 | 2020-10-14 | 64.473 mi |
| Registration #7 | 2020-10-14 | 64.473 mi |
| Registration #8 | 2020-10-14 | 64.473 mi |
| Registration #9 | 2020-10-14 | 64.473 mi |
| Registration #10 | 2020-10-14 | 64.473 mi |

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 85% |
| Pedestrian | 80% |
| Safety systems | 66% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1430 mm |
| Length | 4665 mm |
| Wheel base | 2800 mm |
| Kerb weight | 1720 kg |
| Max. allowed weight | 2145 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 66 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | 2AR1060928 |