



RENAULT

HN03ZPS

report date: 2024-03-29

General information

| | |
|---------------------|--------------------------------|
| Make | RENAULT |
| Model | MEGANE SCENIC FIDJI 16V SCENIC |
| Colour | Red |
| Year of manufacture | - |
| Top speed | 115 mph |
| 0 - 60 mph | 11.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 110 BHP |
| Max. torque | 148 Nm at 3.750 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.5 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 38.7 mpg |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-04 |
| Pictures | 2 |
| Listing price | View report |



source: cargurus.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #19 | 2021-08-05 14:31 |
| MOT test number | 632818533810 |
| Result | ✓ Passed |
| Next expiry date | 2022-08-18 |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Fuel tank support bar corroded |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| | |
|------------------------|---|
| MOT #18 | 2021-08-03 11:17 |
| MOT test number | 356110143024 |
| Result | ✗ Failed |
| Advice | Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Fuel tank support bar corroded |
| Fail | Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Fail | Nearside Front Inner Brake pad(s) incorrectly mounted (1.1.13 (c)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| | |
|------------------------|------------------|
| MOT #17 | 2020-08-18 12:04 |
| MOT test number | 888184683433 |
| Result | ✓ Passed |

| | |
|------------------------|---|
| MOT #16 | 2019-07-23 10:40 |
| MOT test number | 706179473451 |
| Result | ✓ Passed |
| Advice | Nearside Rear brake pads look thin |
| Minor | Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |

**MOT #15** 2018-08-16 12:02**MOT test number** 989234317804**Result** ✓ Passed**MOT #14** 2017-08-18 11:45**MOT test number** 492050352279**Result** ✓ Passed**MOT #13** 2017-08-17 14:07**MOT test number** 965767656777**Result** ✗ Failed**Advice** Both rear tyres walls heavily cracked / perished**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #12** 2016-08-11 11:44**MOT test number** 485452038126**Result** ✓ Passed**Advice** Nearside rear tyre perished on outer sidewall**Advice** Both front tyres worn on inner shoulders**Advice** Rear suspension bar corroded**MOT #11** 2015-08-17 14:34**MOT test number** 248094705184**Result** ✓ Passed

**MOT #10** 2014-08-06 11:59**MOT test number** 217418014233**Result** ✓ Passed**Notice** Slight splits in both front wiper blades**MOT #9** 2013-08-01 11:35**MOT test number** 188213413207**Result** ✓ Passed**Advice** Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Rear cross bar corrodid**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Both front tyres wearing on inner edges**MOT #8** 2012-08-10 12:12**MOT test number** 828333822272**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #7** 2011-08-13 11:49**MOT test number** 665955321255**Result** ✓ Passed**MOT #6** 2010-08-14 11:23**MOT test number** 633306420241**Result** ✓ Passed**MOT #5** 2009-08-19 15:25**MOT test number** 200671339298**Result** ✓ Passed

**MOT #4** 2008-08-14 11:06**MOT test number** 972367728209**Result** ✓ Passed**MOT #3** 2007-05-01 16:26**MOT test number** 553361027161**Result** ✓ Passed**MOT #2** 2007-05-01 12:30**MOT test number** 520661227106**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Advice** Brake disc slightly pitted (3.5.1h)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #1** 2006-05-10 11:20**MOT test number** 864550036100**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2024-03-29 |
| Current registration | ***** |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|---------|------|
| Finance company | RENAULT | 2024 |
| Date of agreement | RENAULT | 2024 |
| Agreement type | RENAULT | 2024 |
| Agreement term | RENAULT | 2024 |
| Agreement number | RENAULT | 2024 |
| Contact info | RENAULT | 2024 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2003-05-23 |
| Last registration | 2021-08-05 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-05-23 | 29 mi |
| Registration #2 | 2006-05-10 | 20.457 mi |
| Registration #3 | 2007-05-01 | 27.405 mi |
| Registration #4 | 2007-05-01 | 27.405 mi |
| Registration #5 | 2008-08-14 | 34.380 mi |
| Registration #6 | 2009-08-19 | 40.178 mi |
| Registration #7 | 2010-08-14 | 43.199 mi |
| Registration #8 | 2011-08-13 | 46.806 mi |
| Registration #9 | 2012-08-10 | 49.582 mi |
| Registration #10 | 2013-08-01 | 52.683 mi |
| Registration #11 | 2014-08-06 | 55.392 mi |
| Registration #12 | 2015-08-06 | 58.101 mi |
| Registration #13 | 2016-08-06 | 60.810 mi |
| Registration #14 | 2017-08-06 | 63.519 mi |
| Registration #15 | 2018-08-06 | 66.228 mi |
| Registration #16 | 2019-08-06 | 68.937 mi |
| Registration #17 | 2020-08-06 | 71.646 mi |
| Registration #18 | 2021-08-06 | 74.355 mi |
| Registration #19 | 2022-08-06 | 77.064 mi |
| Registration #20 | 2023-08-06 | 79.773 mi |
| Registration #21 | 2024-03-29 | 82.482 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|-------------|---------|
| Width | 1698 mm |
| Height | 1675 mm |
| Length | 4169 mm |
| Wheel base | 2580 mm |
| Kerb weight | 1250 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Engine number | D773098 |