



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 2



Date	2022-02-23
Pictures	4
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-06
Pictures	4
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-02-28
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	12
Total items failed	10

MOT #18	2023-02-03 13:22
MOT test number	828205456329
Result	✓ Passed
Next expiry date	2024-02-28
Advice	Nearside Play in steering rack inner joint(s)

MOT #17	2023-02-03 13:22
MOT test number	902049182498
Result	✗ Failed
Advice	Nearside Play in steering rack inner joint(s)
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #16	2022-03-01 08:49
MOT test number	722520567468
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2021-05-14 08:55
MOT test number	349929533014
Result	✓ Passed

**MOT #14** 2021-05-14 08:55**MOT test number** 702800578775**Result** ✗ Failed

**Pass with rectification** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13** 2019-04-09 11:23**MOT test number** 371165046788**Result** ✓ Passed**MOT #12** 2018-04-09 14:57**MOT test number** 998443589948**Result** ✓ Passed**MOT #11** 2018-04-09 10:17**MOT test number** 520087820105**Result** ✗ Failed

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Nearside Front Headlamp not working on main beam (1.7.5a)

**MOT #10** 2017-05-25 08:22**MOT test number** 156151852011**Result** ✓ Passed

**MOT #9** 2017-05-25 07:50**MOT test number** 651952810519**Result** ✓ Passed**MOT #8** 2016-10-25 11:44**MOT test number** 428053612632**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** All 4 tyres slightly perished**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #7** 2015-10-26 09:17**MOT test number** 611612852204**Result** ✓ Passed**MOT #6** 2014-10-29 14:56**MOT test number** 409642604339**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2014-10-29 12:43**MOT test number** 178182404315**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



MOT #4	2013-11-14 10:18
MOT test number	147918313337
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #3	2012-11-30 11:28
MOT test number	148445932307
Result	✓ Passed

MOT #2	2011-09-23 09:39
MOT test number	145216361214
Result	✓ Passed

MOT #1	2010-09-20 10:10
MOT test number	734233360230
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✗  
**MOT**  
**Expired:**  
28 February 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	28 February 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>YP57BWO</b>
Plate since	2019-06-29
Current registration	 <b>YP57BWO</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-10-17
Last registration	2023-02-03
Complete history	<a href="#">See info</a>



Registration #1	2007-10-17	11 mi
Registration #2	2010-09-20	27.553 mi
Registration #3	2011-09-23	32.840 mi
Registration #4	2012-11-30	42.996 mi
Registration #5	2013-11-14	51.175 mi
Registration #6	2014-10-29	58.700 mi
Registration #7	2014-10-29	58.700 mi
Registration #8	2015-10-26	66.565 mi
Registration #9	2016-10-25	72.496 mi
Registration #10	2017-05-25	74.581 mi
Registration #11	2017-05-25	45.123 mi
Registration #12	2018-05-25	55.557 mi
Registration #13	2019-05-25	65.557 mi
Registration #14	2020-05-25	75.557 mi
Registration #15	2021-05-25	85.557 mi
Registration #16	2022-05-25	95.557 mi
Registration #17	2023-05-25	105.557 mi
Registration #18	2024-05-25	115.557 mi
Registration #19	2025-05-25	125.557 mi
Registration #20	2026-05-25	135.557 mi
Registration #21	2027-05-25	145.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 056261