



report date: 2024-03-28

General information

Make	KIA
Model	SOUL CRDI ECHO
Colour	Blue
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-15
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	26
Total items failed	11

MOT #15	2023-06-28 10:26
MOT test number	636507295821
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #14	2022-07-01 10:44
MOT test number	290326356958
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing heavily perished (5.2.3 (d) (ii))

**MOT #13**

2022-06-30 15:09

MOT test number

949359415740

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing heavily perished (5.2.3 (d) (ii))
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #12

2021-05-26 07:08

MOT test number

886049066649

Result**✓ Passed**

- Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2020-06-16 08:23

MOT test number

353927110575

Result**✓ Passed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2019-06-14 13:32**MOT test number** 463969210657**Result** ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9 2019-06-12 14:39**MOT test number** 329980974432**Result** ✗ Failed

Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #8 2018-06-13 09:19**MOT test number** 929752616821**Result** ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7 2018-06-13 09:19**MOT test number** 623480621284**Result** ✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #6 2017-06-16 08:25**MOT test number** 152461314511**Result** ✓ Passed

**MOT #5** 2016-06-14 13:44**MOT test number** 484445397233**Result** ✓ Passed**MOT #4** 2016-06-14 13:44**MOT test number** 146475994340**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2015-06-17 14:56**MOT test number** 849598765122**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-06-17 14:56**MOT test number** 957838065108**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2014-05-09 13:10
MOT test number	828159124163
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
30 June 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		30 June 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LC11CFG
Plate since	2024-03-28
Current registration	LC11CFG
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-05-31
Last registration	2023-06-28
Complete history	See info



Registration #1	2011-05-31	26 mi
Registration #2	2014-05-09	33.246 mi
Registration #3	2015-06-17	38.057 mi
Registration #4	2016-06-14	43.711 mi
Registration #5	2016-06-14	43.711 mi
Registration #6	2017-06-16	49.170 mi
Registration #7	2018-06-13	59.173 mi
Registration #8	2018-06-13	59.173 mi
Registration #9	2019-06-20	65.277 mi
Registration #10	2019-06-20	65.277 mi
Registration #11	2019-06-20	65.277 mi
Registration #12	2019-06-20	65.277 mi
Registration #13	2019-06-20	65.277 mi
Registration #14	2019-06-20	65.277 mi
Registration #15	2019-06-20	65.277 mi
Registration #16	2023-06-28	71.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1429 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBAH532535