






report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC LL29 SPORT DCI
Colour	Silver
Year of manufacture	2011
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 сс
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	37.2 mpg



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-09-10

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2025-01-20
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	30
Total items failed	25

MOT #17		2024-01-11 17:58
MOT test	number	275390739795
Result		✓ Passed
Next expi	ry date	2025-01-20
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16		2024-01-11 17:58
MOT test number		284855957764
Result		× Failed
Advice Oil leak, b	ut not excessive (8.4.1 (a) (i))	
Pass with rectifica	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))		

CarCheck.co.uk page 3/15



MOT #15 2023-01-21 10:23

MOT test number 917144616522

Advice Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre worn on outer edge (5.2.3 (e))

Advice Oil leak, but not excessive engine oil leak (8.4.1 (a) (i))

MOT #14 2023-01-11 15:50

MOT test number 648603179354

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre worn on outer edge (5.2.3 (e))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Advice Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Fail Nearside Headlamp levelling device inoperative (4.1.5 (a))

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Brake cable insecure (1.1.15 (c))

Fail Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Oil leak, but not excessive engine oil leak (8.4.1 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/15



Result

EX11BYC report date: 2024-03-28

X Failed

MOT #13 2022-01-12 07:53

MOT test number 240401992221

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge strongly advise (5.2.3 (e))

MOT #12 2022-01-07 18:15

MOT test number 587562198366

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #11 2021-03-30 15:48

MOT test number 264890939457

Result ✓ Passed

Minor Offside Front Position lamp incorrect colour (4.2.3 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 5/15



EX11BYC

report date: 2024-03-28

MOT #10 2021-03-30 09:35 **MOT** test number 488086598253 Result **X** Failed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Offside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i)) Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Minor Offside Front Position lamp incorrect colour (4.2.3 (a) (i)) Fail Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

 MOT #9
 2019-05-16 12:07

 MOT test number
 842106285929

 Result
 ✓ Passed

MOT #8 2019-05-16 10:15

MOT test number 833398917726

Result X Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

CarCheck.co.uk page 6/15



MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #6

MOT test number

Result

Advice Oil leak

2017-04-24 12:55

228696932438

✓ Passed

MOT test number

Result

Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Advice Oil leak

 MOT #4
 2016-04-25 17:22

 MOT test number
 516171132827

 Result
 ✓ Passed

 MOT #3
 2015-03-10 10:19

 MOT test number
 288089865011

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Notice Nearside front wheel has free play.


CarCheck.co.uk page 7/15



EX11BYC

report date: 2024-03-28





CarCheck.co.uk page 8/15



Tax & MOT check



Tax status

Days left

MOT expiry date

20 January 2025

Full MOT history

See MOT history

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NE ZIN UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-11
Last registration	2024-01-11
Complete history	See info



Registration #1	2011-03-11	24 mi
Registration #2	2014-03-07	46.696 mi
Registration #3	2015-03-10	61.125 mi
Registration #4	2016-04-25	73.319 mi
Registration #5	2017-04-24	82.618 mi
Registration #6	2017-04-24	82.619 mi
Registration #7	2018-05-31	95.041 mi
Registration #8	2019-05-16	107.081 mi
Registration #9	2019-05-16	107.081 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1904 mm
Height	1954 mm
Length	5182 mm
Kerb weight	1907 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	C167735

CarCheck.co.uk page 15/15