





General information

Make	HYUNDAI
Model	IX35 CRDI S BLUE DRIVE
Colour	Black
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	135 g/km
CO2 label	E








Internet history Entry 4 Date 2023-06-28 Pictures 0 Listing price View report

source: carcraft.co.uk

Date	2021-07-10
Pictures	27
Listing price	View report



source: heycar.co.uk

Entry 2	
Date	2021-07-07
Pictures	26
Listing price	View report











source: yesauto.com

Entry 1	
Date	2021-07-05
Pictures	27
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #7	2023-06-28 14:49
MOT test number	441578481303
Result	✓ Passed
Next expiry date	2024-06-27

MOT #6	2023-04-14 10:18
MOT test number	824229222140
Result	✓ Passed
Advice Front brake discs worn and pitted	
Advice Tpms warning lamp - on	
Advice O/s/f suspension arm - play in balljoint	

MOT #5		2022-05-09 13:28
MOT test i	number	489467539645
Result		✓ Passed
Advice	Tpms light on	
Advice	Both rear brake discs worn and discoloured/overheated	
Advice	Front brake discs worn	





MOT #4	2022-	05-06 11:32
MOT test	number 904	031695791
Result		🗙 Failed
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))	
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))	
DANGER	ROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Advice	Tpms light on	
MAJOR	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	
Advice	Both rear brake discs worn and discoloured/overheated	
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	
MAJOR	Service brake efficiency below requirements (1.2.2 (a) (i))	
Advice	Front brake discs worn	

МОТ #3	2021-05-05 10:12
MOT test number	744346196985
Result	✓ Passed
MOT #2	2020-04-14 12:45
MOT test number	442023968509
Result	✓ Passed
MOT #1	2019-05-17 14:22
MOT test number	997827875743
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 27 June 2024
Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E Stand
Date	*
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-21
Last registration	2023-06-28
Complete history	See info



Registration #1	2015-09-21	23 mi
Registration #2	2019-05-17	44.866 mi
Registration #3	2020-04-14	53.705 mi
Registration #4	2021-05-05	61.058 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 mi





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg
Additional information	
Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11