



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-06-02
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-09
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	30
Total items failed	13

MOT #18	2023-05-31 10:33
MOT test number	623556217995
Result	✓ Passed
Next expiry date	2024-06-09

MOT #17	2023-05-31 10:33
MOT test number	737257994245
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #16	2022-05-12 08:11
MOT test number	282535252567
Result	✓ Passed
Advice	Vehicles internal headlight adjuster altered to recheck lights
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Items removed from driver's view prior to test
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #15	2021-06-09 10:21
----------------	------------------

MOT test number	280268290896
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #14	2020-06-10 08:17
----------------	------------------

MOT test number	879105665887
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2019-06-06 12:30
----------------	------------------

MOT test number	513621834016
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
---------------	---

Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
---------------	---

Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
---------------	--

Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
---------------	--

**MOT #12**

2019-06-06 12:30

MOT test number

395969192281

Result

✗ Failed

- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Pass with rectification** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Pass with rectification** Rear Registration plate inscription illegible (0.1 (b))
- Pass with rectification** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Pass with rectification** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Pass with rectification** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #11

2018-06-09 09:51

MOT test number

701903034210

Result

✓ Passed

- Advice** Registration plate deteriorated but not likely to be misread both (0.1 (b))
- Advice** Cannot see inner pads
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** General corrosion

**MOT #10** 2018-06-09 08:42**MOT test number** 208589460372**Result** ✗ Failed**Advice** Registration plate deteriorated but not likely to be misread both (0.1 (b))**Advice** Cannot see inner pads**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** General corrosion**MOT #9** 2017-06-07 11:53**MOT test number** 660837377649**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #8** 2017-06-07 09:55**MOT test number** 608763146229**Result** ✗ Failed**Fail** Offside Headlamp aim too high and too far to the right. (1.8)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2016-06-08 07:57**MOT test number** 578138154367**Result** ✓ Passed**MOT #6** 2015-06-12 11:39**MOT test number** 195513165178**Result** ✓ Passed

**MOT #5** 2012-08-02 15:36**MOT test number** 729425212222**Result** ✓ Passed

- Notice** Front pads look low
- Notice** N/s/f tyre cracking badly and spliting
- Notice** Chips in screen
- Notice** Both rear tyers badly cracking and starting to split

MOT #4 2012-08-02 10:51**MOT test number** 307785712288**Result** ✗ Failed

- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Front pads look low
- Notice** N/s/f tyre cracking badly and spliting
- Notice** Chips in screen
- Notice** Both rear tyers badly cracking and starting to split

MOT #3 2011-08-02 13:02**MOT test number** 748274811273**Result** ✓ Passed**MOT #2** 2010-08-09 14:41**MOT test number** 844631520254**Result** ✓ Passed**MOT #1** 2009-08-18 14:53**MOT test number** 432330239247**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-08-21
Last registration	2023-05-31
Complete history	See info



Registration #1	2006-08-21	13 mi
Registration #2	2009-08-18	7.269 mi
Registration #3	2010-08-09	10.617 mi
Registration #4	2011-08-02	14.863 mi
Registration #5	2012-08-02	17.409 mi
Registration #6	2012-08-02	17.410 mi
Registration #7	2015-06-12	17.751 mi
Registration #8	2016-06-08	22.237 mi
Registration #9	2017-06-07	32.226 mi
Registration #10	2017-06-07	32.226 mi
Registration #11	2019-05-29	35.377 mi
Registration #12	2019-05-29	35.377 mi
Registration #13	2019-05-29	35.377 mi
Registration #14	2019-05-29	35.377 mi
Registration #15	2019-05-29	35.377 mi
Registration #16	2019-05-29	35.377 mi
Registration #17	2019-05-29	35.377 mi
Registration #18	2019-05-29	35.377 mi
Registration #19	2019-05-29	35.377 mi
Registration #20	2019-05-29	35.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU778649