




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI ALTITUDE
Colour	Black
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.0 mpg
CO2 emission	275 g/km
CO2 label	M






Internet history

Entry 3

Date	2021-12-29
Pictures	50
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2


Date	2021-09-10
Pictures	8
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)

Entry 1

Date	2021-09-09
Pictures	13
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-01-10
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	27
Total items failed	4

MOT #18 2024-01-08 15:36**MOT test number** 639056463619**Result** ✓ Passed**Next expiry date** 2025-01-10

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Engine covers and under-trays fitted obscuring some underside components.
- Advice** Steering system slightly rough (2.1.1 (a))
- Advice** Front Coolant leak

MOT #17 2023-01-11 12:15**MOT test number** 896521696039**Result** ✓ Passed

- Advice** Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #16 2021-11-22 14:23**MOT test number** 778796583190**Result** ✓ Passed

- Advice** Power steering operations slightly noisy
- Advice** Power steering operations slightly noisy

**MOT #15** 2020-09-19 12:06**MOT test number** 969545575706**Result** ✓ Passed**MOT #14** 2019-10-08 11:24**MOT test number** 172842593698**Result** ✓ Passed**Advice** Park brake lever not releasing correctly**MOT #13** 2019-10-08 10:19**MOT test number** 703579567823**Result** ✗ Failed**Advice** Park brake lever not releasing correctly**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #12** 2018-10-12 12:29**MOT test number** 502824665439**Result** ✓ Passed**MOT #11** 2018-10-11 10:38**MOT test number** 562782218009**Result** ✗ Failed**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2017-09-29 13:24**MOT test number** 115348421542**Result** ✓ Passed

**MOT #9** 2017-09-25 09:07**MOT test number** 501671496445**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #8 2016-10-12 11:12**MOT test number** 689106354099**Result** ✓ Passed**MOT #7** 2015-08-10 09:18**MOT test number** 598072525274**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #6 2014-07-30 11:34**MOT test number** 518881514274**Result** ✓ Passed

- Notice** Nail in offside rear tyre
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Front tyre worn on inner edge
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Parking brake poor

**MOT #5** 2013-08-07 09:29**MOT test number** 559819113288**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-08-07 09:29**MOT test number** 218909713277**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-08-14 14:31**MOT test number** 337097122446**Result** ✓ Passed**Notice** Front brake discs corroded**Notice** Rear brake discs corroded**MOT #2** 2012-02-02 09:50**MOT test number** 159103632460**Result** ✓ Passed**MOT #1** 2011-03-22 13:17**MOT test number** 368481881056**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
10 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DE08XFK
Plate since	2019-06-29
Current registration	 DE08XFK
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-04-28
Last registration	2024-01-08
Complete history	See info



Registration #1	2008-04-28	7 mi
Registration #2	2011-03-22	45.964 mi
Registration #3	2012-02-02	49.486 mi
Registration #4	2012-08-14	52.624 mi
Registration #5	2013-08-07	61.293 mi
Registration #6	2014-07-30	69.802 mi
Registration #7	2015-08-10	77.884 mi
Registration #8	2016-10-12	85.562 mi
Registration #9	2017-09-25	88.638 mi
Registration #10	2017-09-29	88.740 mi
Registration #11	2018-10-11	94.910 mi
Registration #12	2019-01-01	95.000 mi
Registration #13	2019-01-01	95.000 mi
Registration #14	2019-01-01	95.000 mi
Registration #15	2019-01-01	95.000 mi
Registration #16	2019-01-01	95.000 mi
Registration #17	2019-01-01	95.000 mi
Registration #18	2019-01-01	95.000 mi
Registration #19	2019-01-01	95.000 mi
Registration #20	2019-01-01	95.000 mi
Registration #21	2019-01-01	95.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2230 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2510 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats

5

Engine number

BPE 011351