





report date: 2024-03-29

#### General information

Make	FIAT	
Model	DOBLO 16V SX MULTIJET	
Colour	White	
Year of manufacture	2014	
Top speed	98 mph	
0 - 60 mph	14.9 seconds	
Gearbox	5 speed Manual	

## Engine & fuel consumption

Power	90 BHP	
Max. torque	200 Nm at 1.750 rpm	
Engine capacity	1.248 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	47.9 mpg	
Consumption extra urban	67.3 mpg	
Consumption combined	58.9 mpg	
CO2 emission	126 g/km	
CO2 label	D	



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history


#### Entry 1

Date 2021-11-06

Pictures 27

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

MOT expiry date	2024-11-01
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	7

MOT #10	2023-11-02 15:24
MOT test number	236068902114
Result	✓ Passed
Next expiry date	2024-11-01
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #9		2023-11-02 13:41
MOT te	st number	431527892856
Result		<b>×</b> Failed
Fail	Offside Front Macpherson strut top bush or bearing has excessive wear or free p	lay (5.3.4 (a) (i))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))		
Mino	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (	i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2022-11-01 09:38 **MOT** test number 861265503211 Result × Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) **Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #6	2021-10-15 08:07
MOT test number	974171071553
Result	<b>✓</b> Passed
MOT #5	2020-10-28 12:08
MOT test number	620288149129
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2019-10-30 13:03

**MOT test number** 594210030530

**Result** ✓ Passed

MOT #3 2019-10-30 11:55

MOT test number 180262936900

**Result** X Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2018-10-30 10:29

**MOT test number** 987352982186

**Result** 
✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge border line (5.2.3 (e))

MOT #1 2017-11-02 09:02

**MOT test number** 390226137661

Result 

Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	1 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

Owner mistory	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
*******	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	ZIS UK
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact mio

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-10-16
Last registration	2023-11-02
Complete history	See info



Registration #1	2014-10-16	12 mi
Registration #2	2017-11-02	45.964 mi
Registration #3	2018-10-30	60.438 mi
Registration #4	2019-10-30	71.499 mi
Registration #5	2019-10-30	71.502 mi
Registration #6	2020-10-28	82.494 mi
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1345 kg
Max. allowed weight	2325 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number Carcheck.co.uk	5475238 page 12/12