



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	Orange
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-07-17
Pictures	31
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-14
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	30
Total items failed	13

MOT #16	2024-01-15 11:58
MOT test number	424068975227
Result	✓ Passed
Next expiry date	2025-01-14
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2024-01-15 11:14
MOT test number	920269891341
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #14**

2023-01-12 13:58

MOT test number

118537163852

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view Chips in zone A and B (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #13

2023-01-06 16:16

MOT test number

173894884996

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view Chips in zone A and B (3.2 (a) (i))
- Fail** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12** 2022-01-04 10:35**MOT test number** 505762399482**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-01-07 10:12**MOT test number** 652307441484**Result** ✓ Passed**MOT #10** 2021-01-07 09:50**MOT test number** 943374332518**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2021-01-06 16:15**MOT test number** 436451202272**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2019-10-23 14:18**MOT test number** 946028780044**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-11-05 10:57**MOT test number** 336412161229**Result** ✓ Passed

**MOT #6** 2017-11-01 09:30**MOT test number** 252552030200**Result** ✓ Passed**Advice** Engine and under covers fitted**MOT #5** 2016-11-07 10:19**MOT test number** 968746515252**Result** ✓ Passed**MOT #4** 2015-11-03 16:36**MOT test number** 681502296047**Result** ✓ Passed**MOT #3** 2015-11-03 11:03**MOT test number** 953185008229**Result** ✗ Failed**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #2** 2014-10-27 11:00**MOT test number** 345700604375**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #12014-10-27 11:00

MOT test number728310804337

ResultX Failed

AdviceOffside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectificationNearside Headlamp not working on dipped beam (1.7.5a)

AdviceNearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

AdviceFront registration plate deteriorated but not likely to be misread (6.3.1d)

Pass with rectificationFront Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:
18 April 2024

✓

MOT

Expires:
14 January 2025

Tax status	Expired at 18 April 2024
Days left	10 days too late
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BJ61YYK
Plate since	2024-03-29
Current registration	BJ61YYK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-11-16
Last registration	2024-01-15
Complete history	See info



Registration #1	2011-11-16	25 mi
Registration #2	2014-10-27	121.877 mi
Registration #3	2015-11-03	130.441 mi
Registration #4	2015-11-03	130.442 mi
Registration #5	2016-11-07	133.242 mi
Registration #6	2017-11-01	138.360 mi
Registration #7	2018-11-05	152.046 mi
Registration #8	2019-10-23	162.713 mi
Registration #9	2021-01-06	166.783 mi
Registration #10	2022-01-06	166.783 mi
Registration #11	2022-01-06	166.783 mi
Registration #12	2022-01-06	166.783 mi
Registration #13	2022-01-06	166.783 mi
Registration #14	2022-01-06	166.783 mi
Registration #15	2022-01-06	166.783 mi
Registration #16	2022-01-06	166.783 mi
Registration #17	2022-01-06	166.783 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212