





### General information

Make	KIA
Model	CARENS GS CRDI
Colour	Blue
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 1.800 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G







Internet history	
Entry 1	
Date	2021-01-31
Pictures	0
Listing price	View report

source: autoonline.co.uk



# MOT history

MOT expiry date	2022-02-28
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	33
Total items failed	17

MOT #17	2021-03-01 14:19
MOT test number	709296534816
Result	🗸 Passed
Next expiry date 2022-02-	
Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #16	20	019-07-02 10:24
MOT test	number	226423998445
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		





MOT #15		2018-06-01 13:16
MOT test	number	610314745362
Result		✓ Passed
<b>Advice</b> frontmost	Offside Front Lower Suspension arm pin or bush worn but not resulting in excess (5.3.4 (a) (i))	sive movement
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	





MOT #14	2018-06-01 13:16	
MOT test number	736748620380	
Result	× Failed	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))	
Advice Rear Brake pad(	s) wearing thin (1.1.13 (a) (ii))	
Pass with rectification (b) (ii))	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4	
Advice Nearside Rear B	rake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Front Brake pad	(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Low frontmost (5.3.4 (a) (i))	wer Suspension arm pin or bush worn but not resulting in excessive movement	
Pass with rectification	Offside Headlamp not working on main beam (4.1.1 (a) (ii))	
Advice Offside Front Bra	ake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a))	
<b>Pass with rectification</b> (b) (ii))	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4	
Advice Offside Rear Bra	ke disc worn, but not excessively (1.1.14 (a) (i))	
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

МОТ #13	2017-06-08 11:14
MOT test number	182895816123
Result	✓ Passed

MOT #12		2017-06-08 11:14
MOT test number		508705600650
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high and too far to the right. (1.8)	





MOT #11	2016-06-28 11:21
MOT test number	751180342461
Result	✓ Passed
MOT #10	2016-06-27 08:05
MOT test number	671136696267
Result	🗙 Failed
Fail         Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail         Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

МОТ #9	2015-06-11 17:08
MOT test number	219992565488
Result	✓ Passed

MOT #8	2015-06-11 10:46
MOT test number	849042065143
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
FailParking brake lever has no reserve travel (3.1.6b)	
FailOffside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
<b>Fail</b> Offside Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Advice



MOT #7	2014-06-25 15:30
MOT test number	765046774169
Result	✓ Passed
MOT #6	2013-07-09 11:09
MOT test number	446820693165
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #5	2013-07-09 11:09
MOT test number	938970793142
Result	× Failed
Advice Offside Front Ty	re worn close to the legal limit (4.1.E.1)
<b>Pass with rectification</b> (8.2.2)	Nearside Front Windscreen wiper does not clear the windscreen effectively
Advice Nearside Front	yre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4		2012-06-12 12:12
MOT test	number	707424262121
Result		✓ Passed
Notice	Osf tyre edge worn	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Notice	Front brake pads getting low	





MOT #3		2011-06-14 15:28
MOT test	number	328055361199
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2011-06-14 09:15
MOT test number	906085761187
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
FailParking brake lever has no reserve travel (3.1.6b)	
Pass with rectificationOffside Headlamp aim too high (1.8)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectification         Nearside Headlamp aim too high (1.8)	

MOT #1	2010-09-28 16:33
MOT test number	371591670494
Result	✓ Passed





Tax & MOT check

X Untaxed Tax expired: 13 April 2019	<b>X</b> <b>MOT</b> Expired: 28 February 2022
Tax status	Expired at 13 April 2019
Days left	1842 days too late
MOT expiry date	28 February 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Number of plates Carrent registration	
Number of plates Carrent registration	
Romber of plates Correct registration Fals since Correct registration	
Number of plates Correct registration Fals since Fals since Fals since	8000-20-20





### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-02-18
Last registration	2021-03-01
Complete history	See info



Registration #1	2008-02-18	18 mi
Registration #2	2010-09-28	8.493 mi
Registration #3	2011-06-14	17.093 mi
Registration #4	2011-06-14	17.093 mi
Registration #5	2012-06-12	31.236 mi
Registration #6	2013-07-09	45.846 mi
Registration #7	2014-06-25	59.807 mi
Registration #8	2015-06-11	73.062 mi
Registration #9	2015-06-11	73.068 mi
Registration #10		11.777 est
Registration #11		11.707 esi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.117 esi





### Car features

S0225	Air conditionin
S0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1657 kg
Max. allowed weight	2255 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/15