



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI + CDTI 150
Colour	Silver
Year of manufacture	-
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	315 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #15	2021-01-29 14:28
MOT test number	962724515533
Result	✓ Passed
Next expiry date	2022-01-28
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14	2021-01-27 15:14
MOT test number	208955311745
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Parking brake inoperative on one side (1.4.1 (a))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13	2019-07-22 08:06
MOT test number	802338070166
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2018-08-01 15:57**MOT test number** 704602868485**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2017-07-31 10:05**MOT test number** 941544295159**Result** ✓ Passed**MOT #10** 2016-06-08 12:58**MOT test number** 151536448843**Result** ✓ Passed

- Advice** Both front tyres inner edges worn

MOT #9 2015-06-04 09:51**MOT test number** 408465655135**Result** ✓ Passed**MOT #8** 2014-06-10 14:55**MOT test number** 798551964123**Result** ✓ Passed

- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #7** 2013-06-05 15:38**MOT test number** 495016853155**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-06-05 15:38**MOT test number** 606226253158**Result** ✗ Failed**Pass with rectification** Offside Rear coil spring incomplete (2.4.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-05-31 09:19**MOT test number** 879962552108**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-06-14 10:53**MOT test number** 578055461108**Result** ✓ Passed**Advice** Nearside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2010-06-18 15:26**MOT test number** 953249760100**Result** ✓ Passed



MOT #2 2010-06-18 10:14

MOT test number 403179860138

Result ✗ Failed

Notice Nail in nearside rear tyre

Fail Front registration plate character(s) incorrectly spaced (6.3.4a)

Fail Front registration plate character(s) laid out in an incorrect format (6.3.4f)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Rear registration plate character(s) incorrectly spaced (6.3.4a)

Fail Rear registration plate character(s) laid out in an incorrect format (6.3.4f)

MOT #1 2009-05-26 14:24

MOT test number 600906549188

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-29
Current registration	 XXXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-06-16
Last registration	2021-01-29
Complete history	See info



Registration #1	2006-06-16	25 mi
Registration #2	2009-05-26	36.067 mi
Registration #3	2010-06-18	47.972 mi
Registration #4	2010-06-18	47.972 mi
Registration #5	2011-06-14	58.126 mi
Registration #6	2012-05-31	67.974 mi
Registration #7	2013-06-05	78.871 mi
Registration #8	2014-06-10	87.858 mi
Registration #9	2015-06-10	96.845 mi
Registration #10	2016-06-10	105.832 mi
Registration #11	2017-06-10	114.819 mi
Registration #12	2018-06-10	123.806 mi
Registration #13	2019-06-10	132.793 mi
Registration #14	2020-06-10	141.780 mi
Registration #15	2021-01-29	150.767 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1753 mm
Height	1413 mm
Length	4288 mm
Wheel base	2614 mm
Kerb weight	1343 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	17090635