



report date: 2024-03-29

General information

Make	AUDI
Model	A5 TFSI
Colour	Silver
Year of manufacture	2009
Top speed	148 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	180 BHP
Max. torque	320 Nm at 3.900 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G





## MOT history

MOT expiry date	2025-04-14
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	38
Total items failed	2

MOT #17	2024-04-09 15:13
MOT test number	406320934726
Result	✓ Passed
Next expiry date	2025-04-14

MOT #16	2023-04-15 14:01
MOT test number	173420746255
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))

MOT #15	2022-04-11 11:58
MOT test number	994325813015
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))

**MOT #14** 2022-04-09 11:05**MOT test number** 231613517030**Result** ✗ Failed

- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
- MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))

**MOT #13** 2021-04-13 15:00**MOT test number** 765411390721**Result** ✓ Passed**MOT #12** 2021-04-03 09:15**MOT test number** 956160023413**Result** ✗ Failed

- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #11** 2020-03-24 11:08**MOT test number** 564332055980**Result** ✓ Passed

- Advice** Central exhaust sleeve corroded /broken
- Advice** Under trays fitted
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Engine covers fitted

**MOT #10** 2019-03-27 11:30**MOT test number** 601835818062**Result** ✓ Passed**Advice** Under trays fitted**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine covers fitted**MOT #9** 2019-03-22 11:26**MOT test number** 383334012234**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Under trays fitted**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Engine covers fitted**MOT #8** 2018-03-12 10:16**MOT test number** 793779636339**Result** ✓ Passed**Advice** Rear brake pads wearing low**Advice** Nearside Rear tyre on 2mm**Advice** Centre exhaust sleeve rusty**Advice** Nearside Front tyre on 2mm

**MOT #7** 2017-03-13 12:15**MOT test number** 357734350319**Result** ✓ Passed**Advice** Offside Front tyre side wall damaged**MOT #6** 2016-03-15 10:40**MOT test number** 750692630042**Result** ✓ Passed**Advice** Offside Front condensation in head light unit**Advice** Offside Rear Tyre worn close to the legal limit on 2mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)**MOT #5** 2015-03-26 11:44**MOT test number** 387595485048**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** NSR tyre worn on inner edge**MOT #4** 2014-03-26 08:46**MOT test number** 637565584038**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #3** 2014-03-25 15:39**MOT test number** 898134184077**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #2** 2013-02-26 09:22**MOT test number** 115757553407**Result** ✓ Passed**MOT #1** 2012-03-13 16:57**MOT test number** 955503272082**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
14 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	14 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	<b>YD09LJY</b>
Plate since	2019-03-29
Current registration	<b>YD09LJY</b>
Plate since	2019-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-05
Last registration	2024-04-09
Complete history	<a href="#">See info</a>



Registration #1	2009-03-05	11 mi
Registration #2	2012-03-13	17.867 mi
Registration #3	2013-02-26	22.453 mi
Registration #4	2014-03-25	34.348 mi
Registration #5	2014-03-26	34.348 mi
Registration #6	2015-03-26	46.152 mi
Registration #7	2016-03-15	54.100 mi
Registration #8	2017-03-13	60.600 mi
Registration #9	2018-03-12	67.209 mi
Registration #10	2019-03-20	75.277 mi
Registration #11	2020-03-20	85.277 mi
Registration #12	2021-03-20	95.277 mi
Registration #13	2022-03-20	105.277 mi
Registration #14	2023-03-20	115.277 mi
Registration #15	2024-03-20	125.277 mi
Registration #16	2025-03-20	135.277 mi
Registration #17	2026-03-20	145.277 mi
Registration #18	2027-03-20	155.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1854 mm
Height	1495 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1420 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	CDN 039425