



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	197 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-12
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-01
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	20
Total items failed	8

MOT #13	2023-08-18 11:58
MOT test number	788353519250
Result	✓ Passed
Next expiry date	2024-09-01
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view chipped in zone A (3.2 (a) (i))

MOT #12	2023-08-14 09:44
MOT test number	155427156110
Result	✗ Failed
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Front Light intensity reduced,bulb issue
Minor	Front Windscreen wiper blade defective both front wipers splitting (3.4 (b) (i))
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Fail	Nearside Front Position lamp not working sidelight (4.2.1 (a) (ii))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view chipped in zone A (3.2 (a) (i))

**MOT #11**

2022-08-30 14:41

MOT test number

402538948177

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #10

2021-08-17 10:44

MOT test number

398830112010

Result

✓ Passed

MOT #9

2020-08-19 11:14

MOT test number

870803316275

Result

✓ Passed

Advice Shock absorbers light misting of oil or has limited damping effect both rear (5.3.2 (b))

MOT #8

2019-08-07 08:48

MOT test number

348274350987

Result

✓ Passed

**MOT #7** 2019-08-06 12:19**MOT test number** 795548650777**Result** ✗ Failed**Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #6** 2018-08-15 14:25**MOT test number** 647677898844**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2018-08-15 09:14**MOT test number** 564335659400**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #4** 2017-08-29 10:12**MOT test number** 699684839077**Result** ✓ Passed**MOT #3** 2016-09-02 13:03**MOT test number** 275076732771**Result** ✓ Passed



MOT #2	2016-09-02 13:03
MOT test number	161309883618
Result	✗ Failed
Pass with rectification	Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
Pass with rectification	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1	2015-10-30 10:19
MOT test number	601596829718
Result	✓ Passed
Advice	Brake pad(s) wearing thin Front and rear (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 September 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	FL62ZXE
Plate since	2024-03-29
Current registration	FL62ZXE
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-31
Last registration	2023-08-18
Complete history	See info



Registration #1	2012-10-31	6 mi
Registration #2	2015-10-30	41.465 mi
Registration #3	2016-09-02	54.153 mi
Registration #4	2016-09-02	54.153 mi
Registration #5	2017-08-29	70.685 mi
Registration #6	2018-08-15	86.615 mi
Registration #7	2018-08-15	86.616 mi
Registration #8	2019-08-06	99.729 mi
Registration #9	2019-08-06	99.729 mi
Registration #10	2019-08-06	99.729 mi
Registration #11	2019-08-06	99.729 mi
Registration #12	2019-08-06	99.729 mi
Registration #13	2019-08-06	99.729 mi
Registration #14	2019-08-06	99.729 mi
Registration #15	2019-08-06	99.729 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	D4HBCU614953
---------------	--------------