



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------|
| Make | FORD |
| Model | FOCUS C-MAX STYLE 100 |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 107 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 100 BHP |
| Max. torque | 145 Nm at 4.000 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.9 mpg |
| CO2 emission | 164 g/km |
| CO2 label | G |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-11-24 |
| MOT pass rate | 76 % |
| MOT passed | 13 |
| Failed MOT tests | 4 |
| Total advice items | 23 |
| Total items failed | 4 |

| | |
|------------------|------------------|
| MOT #17 | 2022-11-25 13:48 |
| MOT test number | 571004598128 |
| Result | ✓ Passed |
| Next expiry date | 2023-11-24 |

| | |
|-----------------|--|
| MOT #16 | 2021-11-25 13:32 |
| MOT test number | 802961779867 |
| Result | ✓ Passed |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

| | |
|-----------------|--|
| MOT #15 | 2020-11-18 10:03 |
| MOT test number | 979214026725 |
| Result | ✓ Passed |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Both side rear disc & pads slight worn |
| Advice | Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e)) |
| Advice | Headlamp has a product on the lens but not seriously reducing light output both side (4.1.4 (b)) |

**MOT #14** 2019-05-24 05:41**MOT test number** 964898802626**Result** ✓ Passed**Advice** Nearside Front Track rod end slightly misaligned (2.1.3 (e))**Advice** Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13** 2018-05-23 10:31**MOT test number** 407762438469**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #12** 2017-05-24 16:06**MOT test number** 570939620957**Result** ✓ Passed**MOT #11** 2016-05-05 15:13**MOT test number** 765189910837**Result** ✓ Passed**MOT #10** 2016-05-05 10:38**MOT test number** 666266147172**Result** ✗ Failed**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #9** 2015-07-02 16:16**MOT test number** 577913685100**Result** ✓ Passed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Both front tyres worn on inner & outer edges**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #8** 2015-07-02 11:00**MOT test number** 345313385173**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Both front tyres worn on inner & outer edges**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #7** 2014-06-20 13:23**MOT test number** 179191074120**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2013-01-24 14:38**MOT test number** 917334423059**Result** ✓ Passed

**MOT #5** 2013-01-24 14:38**MOT test number** 696314923076**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2012-01-25 13:15**MOT test number** 535305722086**Result** ✓ Passed**MOT #3** 2012-01-24 12:18**MOT test number** 838524622040**Result** ✗ Failed**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #2** 2011-02-16 11:47**MOT test number** 855997041035**Result** ✓ Passed**MOT #1** 2010-03-08 15:56**MOT test number** 553437760017**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Near side rear reflector broken**Notice** Off side rear tyre has a flat spot



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
24 November 2023

| | |
|------------------|---------------------------------|
| Tax status | Expired at 1 March 2024 |
| Days left | 58 days too late |
| MOT expiry date | 24 November 2023 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | WU07HLW |
| Plate since | 2019-09-28 |
| Current registration | WU07HLW |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2007-04-24 |
| Last registration | 2022-11-25 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-04-24 | 10 mi |
| Registration #2 | 2010-03-08 | 13.547 mi |
| Registration #3 | 2011-02-16 | 18.999 mi |
| Registration #4 | 2012-01-24 | 23.667 mi |
| Registration #5 | 2012-01-25 | 23.667 mi |
| Registration #6 | 2013-01-24 | 31.104 mi |
| Registration #7 | 2014-06-20 | 42.106 mi |
| Registration #8 | 2015-07-02 | 51.675 mi |
| Registration #9 | 2016-06-20 | 55.377 mi |
| Registration #10 | 2017-06-20 | 59.377 mi |
| Registration #11 | 2018-06-20 | 63.377 mi |
| Registration #12 | 2019-06-20 | 67.377 mi |
| Registration #13 | 2020-06-20 | 71.377 mi |
| Registration #14 | 2021-06-20 | 75.377 mi |
| Registration #15 | 2022-11-25 | 79.377 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2022 mm |
| Height | 1595 mm |
| Length | 4333 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1372 kg |
| Max. allowed weight | 1855 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|---------|
| Number of axles | 2 |
| Engine number | 7J32215 |