



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Grey
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-07
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-08
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #15	2023-12-04 11:20
MOT test number	806901763356
Result	✓ Passed
Next expiry date	2024-12-08

MOT #14	2022-12-01 14:55
MOT test number	915422558452
Result	✓ Passed

MOT #13	2021-12-02 13:04
MOT test number	949708036521
Result	✓ Passed

MOT #12	2020-12-09 12:40
MOT test number	856016680679
Result	✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2019-11-27 15:27**MOT test number** 930274022265**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Offside & Nearside (1.1.14 (a) (ii))

MOT #10 2019-11-27 14:17**MOT test number** 637810445352**Result** ✗ Failed

Fail Rear Brake pad(s) less than 1.5 mm thick Offside worn more than Nearside (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Offside & Nearside (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Offside & Nearside (1.1.14 (a) (ii))

MOT #9 2018-11-27 11:54**MOT test number** 323102200036**Result** ✓ Passed**MOT #8** 2018-11-27 11:54**MOT test number** 868497931616**Result** ✗ Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #7** 2017-11-27 11:14**MOT test number** 804186857782**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2016-11-30 17:16**MOT test number** 346870903831**Result** ✓ Passed**MOT #5** 2016-11-30 13:03**MOT test number** 785464841153**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2015-10-23 14:02**MOT test number** 735335310925**Result** ✓ Passed**MOT #3** 2015-02-11 14:50**MOT test number** 457802445029**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-09-05 09:05**MOT test number** 325928843411**Result** ✓ Passed



MOT #1	2012-08-13 12:14
MOT test number	339006222256
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
8 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	OU59YWE
Plate since	2019-03-29
Current registration	OU59YWE
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-01
Last registration	2023-12-04
Complete history	See info



Registration #1	2009-09-01	22 mi
Registration #2	2012-08-13	20.229 mi
Registration #3	2013-09-05	27.723 mi
Registration #4	2015-02-11	45.817 mi
Registration #5	2015-10-23	55.431 mi
Registration #6	2016-11-30	62.650 mi
Registration #7	2016-11-30	62.650 mi
Registration #8	2017-11-27	69.813 mi
Registration #9	2018-11-27	76.741 mi
Registration #10	2019-05-29	85.377 mi
Registration #11	2019-05-29	85.377 mi
Registration #12	2019-05-29	85.377 mi
Registration #13	2019-05-29	85.377 mi
Registration #14	2019-05-29	85.377 mi
Registration #15	2019-05-29	85.377 mi
Registration #16	2019-05-29	85.377 mi
Registration #17	2019-05-29	85.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CGG 116680