





report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Silver
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-24

Pictures 34

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT h	nistory
-------	---------

MOT expiry date	2024-06-01
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	19
Total items failed	9

MOT #19	2023-06-02 15:13
MOT test number	306605422415
Result	✓ Passed
Next expiry date	2024-06-01

MOT #18		2023-06-02 15:13
MOT test number		977637032635
Result		X Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #17	2022-05-31 13:28
MOT test number	394769686282
Result	✓ Passed

MOT #16	2022-05-30 14:05
MOT test number	490277209211
Result	X Failed
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #15

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #14

MOT test number

Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #13 2020-06-02 14:13 **MOT** test number 273571649549 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Drive shaft joint worn, but not excessively (6.1.7 (c) (i)) **Advice** Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Offside Rear Brake pipe corroded, covered in grease or other material slight corrosion appearing (1.1.11(c))**Advice** Offside Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

MOT #12	2019-04-26 13:37
MOT test number	552178557407
Result	✓ Passed

MOT #11	2018-04-19 12:58
MOT test number	761050254709
Result	✓ Passed

CarCheck.co.uk page 4/14



(3.5.1i)

(3.5.1i)

AU07VPA

report date: 2024-03-28

MOT #10 2017-04-25 13:40

MOT test number 642691216935

MOT #9 2016-04-27 13:53

MOT test number 647257570955

Result

Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides worn and ridged

Advice Nearside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)

MOT #8 2016-04-26 15:07

MOT test number 115931362773

Result X Failed

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

Fail Offside Rear Tyre has ply or cords exposed perished in tread and split open (4.1.D.1b)

Fail Rear Exhaust system not adequately supported bracket rusted away (7.1.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides worn and ridged

MOT #7 2015-04-24 15:24

MOT test number 868604215194

Result
✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)

Notice Rear exhaust strap broken advise repair

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT test number

456528814153

Result

Notice | Near side front tyre wearing on outer edge almost through too rienforcement advise change soon.

Notice | Rear silencer mounting band corroded & broken but still adequatly supported

MOT #4

MOT test number

Result

Notice Rear silencer strap broken but still adequatly supported, advise have checked soon.

MOT #3

MOT test number

786424012125

Result

✓ Passed

MOT #2

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2010-04-16 11:12

MOT test number 670366900179

Result ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Plate since

AU07VPA

report date: 2024-03-28

UK UK

More info >

Owner history		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full re		ROEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	OK SIE	
Plate since		

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-27
Last registration	2023-06-02
Complete history	See info



Registration #1	2007-04-27	29 mi
Registration #2	2010-04-16	28.373 mi
Registration #3	2011-04-07	33.831 mi
Registration #4	2012-04-23	39.812 mi
Registration #5	2013-04-24	47.220 mi
Registration #6	2014-04-28	56.798 mi
Registration #7	2015-04-24	65.103 mi
Registration #8	2015-04-24	65.103 mi
Registration #9	2016-04-26	73.031 mi
Registration #10	2016-04-27	73.035 mi
Registration #11	2017-04-25	80.441 mi
Registration #12		11.777 es
Registration #12 Registration #13		11,777 ea 11,777 ea
-		11.77 m 11.77 m
Registration #13		11.777 ea 11.777 ea 11.777 ea
Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11,777 est

More info >

CarCheck.co.uk page 13/14



AU07VPA report date: 2024-03-28

Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543

CarCheck.co.uk page 14/14