



J190RN

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ST-3
Colour	Black
Year of manufacture	2010
Top speed	150 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	223 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





## MOT history

MOT expiry date	2025-02-23
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	22
Total items failed	5

MOT #17	2024-02-24 10:12
MOT test number	367159608904
Result	✓ Passed
Next expiry date	2025-02-23
Advice	Age related corrosion on rear suspension

MOT #16	2023-02-02 19:34
MOT test number	424874504785
Result	✓ Passed

MOT #15	2023-02-02 19:34
MOT test number	565328248807
Result	✗ Failed
Pass with rectification	Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14	2022-02-08 12:53
MOT test number	777211764440
Result	✓ Passed
Advice	Anti-roll bar linkage ball joint has slight play both rear (5.3.4 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #13	2021-02-09 15:50
MOT test number	878020856109
Result	✓ Passed
MOT #12	2020-01-22 16:10
MOT test number	918353390351
Result	✓ Passed
MOT #11	2020-01-20 16:31
MOT test number	428038899474
Result	✗ Failed
<div><div>DANGEROUS</div><div>Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div></div> <div><div>DANGEROUS</div><div>Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div></div>	
MOT #10	2019-09-10 17:47
MOT test number	687556416961
Result	✓ Passed
<div><div>Advice</div><div>Advise wear offside rear axle bush</div></div>	

**MOT #9** 2019-09-09 15:05**MOT test number** 376009540448**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Advise wear offside rear axle bush**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #8** 2017-04-06 15:35**MOT test number** 332527046400**Result** ✓ Passed**MOT #7** 2016-04-01 16:06**MOT test number** 885318525434**Result** ✓ Passed**MOT #6** 2015-04-04 11:44**MOT test number** 819354595018**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2015-04-04 11:44**MOT test number** 827074295068**Result** ✗ Failed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Pass with rectification** Nearside Side repeater not working (1.4.A.2c)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2014-04-03 10:22**MOT test number** 886513594029**Result** ✓ Passed**MOT #3** 2013-03-20 12:21**MOT test number** 428329173054**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-11-05 11:36**MOT test number** 486350912484**Result** ✓ Passed**MOT #1** 2012-11-05 11:36**MOT test number** 488520912481**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Offside Front Headlamp aim too high (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
23 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	23 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-15
Last registration	2024-02-24
Complete history	<a href="#">See info</a>



Registration #1	2010-03-15	15 mi
Registration #2	2012-11-05	23.587 mi
Registration #3	2013-03-20	26.574 mi
Registration #4	2014-04-03	34.259 mi
Registration #5	2015-04-04	42.246 mi
Registration #6	2016-04-01	49.154 mi
Registration #7	2017-04-06	54.440 mi
Registration #8	2019-09-09	60.056 mi
Registration #9	2020-05-20	65.000 mi
Registration #10	2020-05-20	65.000 mi
Registration #11	2020-05-20	65.000 mi
Registration #12	2020-05-20	65.000 mi
Registration #13	2020-05-20	65.000 mi
Registration #14	2020-05-20	65.000 mi
Registration #15	2020-05-20	65.000 mi
Registration #16	2020-05-20	65.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1839 mm
Height	1497 mm
Length	4357 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	AU03984