



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Black
Year of manufacture	2008
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-15
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-31
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #16	2024-03-20 10:31
MOT test number	259780792511
Result	✓ Passed
Next expiry date	2025-03-31

MOT #15	2023-03-17 09:07
MOT test number	617548745858
Result	✓ Passed
Advice	Direction indicator slightly discoloured both rear (4.4.3 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2022-03-23 16:55
MOT test number	430957917300
Result	✓ Passed

**MOT #13** 2021-04-01 08:04**MOT test number** 467586164975**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Both front tyres wearing inner edges
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing badly perished inner side wall (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

**MOT #12** 2019-05-15 10:52**MOT test number** 123369566007**Result** ✓ Passed

- Advice** Front Tyre slightly damaged/cracking or perishing nearside and offside in tread (5.2.3 (d) (ii))

**MOT #11** 2018-04-30 09:48**MOT test number** 594229605064**Result** ✓ Passed**MOT #10** 2018-04-30 09:48**MOT test number** 478634706797**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too low (1.8)

**MOT #9** 2017-05-12 08:55**MOT test number** 418486863383**Result** ✓ Passed

**MOT #8** 2017-05-11 16:43**MOT test number** 947720991015**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2016-09-20 09:14**MOT test number** 270817686667**Result** ✓ Passed**Advice** Handbrake travel inner joints utray fitted engine cover fitted**MOT #6** 2015-09-16 10:11**MOT test number** 105800981437**Result** ✓ Passed**MOT #5** 2014-09-20 11:54**MOT test number** 246393364284**Result** ✓ Passed**MOT #4** 2014-09-20 11:54**MOT test number** 848343864217**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)



MOT #3	2013-09-21 17:06
MOT test number	395824363263
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-06-22 13:09
MOT test number	979663273127
Result	✓ Passed
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-06-23 12:53
MOT test number	959885372103
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
31 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	31 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>LT58KDN</b>
Plate since	2019-06-29
Current registration	 <b>LT58KDN</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-04
Last registration	2024-03-20
Complete history	<a href="#">See info</a>



Registration #1	2008-09-04	9 mi
Registration #2	2012-06-23	21.114 mi
Registration #3	2013-06-22	23.547 mi
Registration #4	2013-09-21	24.293 mi
Registration #5	2014-09-20	27.343 mi
Registration #6	2015-09-16	29.961 mi
Registration #7	2016-09-20	32.025 mi
Registration #8	2017-05-11	32.735 mi
Registration #9	2017-05-12	32.735 mi
Registration #10	2019-05-20	35.377 mi
Registration #11	2019-05-20	35.377 mi
Registration #12	2019-05-20	35.377 mi
Registration #13	2019-05-20	35.377 mi
Registration #14	2019-05-20	35.377 mi
Registration #15	2019-05-20	35.377 mi
Registration #16	2019-05-20	35.377 mi
Registration #17	2019-05-20	35.377 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431089315