

Ford



General information

Make	FORD
Model	FOCUS EDGE TDCI
Colour	Silver
Year of manufacture	2014
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	В







Internet history

Entry 2	
Date	2022-02-01
Pictures	29
Listing price	<u>View report</u>









source: autotrader.co.uk

Entry 1

Date

Pictures

Listing price

25 <u>View report</u>

2022-01-14



source: yesauto.com









MOT history

MOT expiry date	2024-02-09
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #8		2023-02-07 11:45
MOT test	number	879048717326
Result		✓ Passed
Next expi	ry date	2024-02-09
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #7	2022-01-10 16:36
MOT test number	999287307501
Result	✓ Passed
MOT #6	2022-01-10 16:35
MOT test number	295141846240

Pass with rectification

Front Registration plate insecure (0.1 (a))

Result

🗙 Failed





MOT #5	2021-02-01 08:30
MOT test number	991293340866
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened 2 (2	1.1.14 (a) (ii))
MOT #4	2020-02-10 08:23
MOT test number	219908806317
Result	✓ Passed
Advice 1/ front brake discs becoming corroded on inside edge	
MOT #3	2019-04-09 11:53
MOT test number	203191664356
Result	Passed
MOT #2 MOT test number	2018-04-30 13:16 386642928150
Result	300042920130 ✓ Passed
Nesure	V Tusseu
MOT #1	2017-04-25 10:44
MOT test number	923126211388
Result	✓ Passed
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice Offside Front Tyre worn close to the legal limit 2.2mm (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit 2.4mm (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	X MOT 9 February 2024
Tax status	Valid until 1 February
Days left	279
MOT expiry date	9 February 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrient registration	
Current registration Pate since	
Carrent registration Fate since Carrent registration	
Carrent registration Foto since Foto since Foto since	8000-20-20





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-06-26
Last registration	2023-02-07
Complete history	See info



Registration #1	2014-06-26	18 mi
Registration #2	2017-04-25	31.302 mi
Registration #3	2018-04-30	37.770 mi
Registration #4	2019-04-09	43.559 mi
Registration #5	2020-02-10	51.183 mi
Registration #6	2021-02-01	53.373 mi
Registration #7		11.777 esi
Registration #8		11.117 esi
Registration #9		11.117 esi
Registration #10		11.777 esi
Registration #11		11.117 esi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	82%
Pedestrian	72%
Safety systems	71%
Overall rating	84%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2010 mm
Height	1492 mm
Length	4560 mm
Wheel base	2648 mm
Max. allowed weight	1900 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

DK00787