





report date: 2024-03-28

#### General information

Make	FORD
Model	C-MAX ZETEC TDCI
Colour	Black
Year of manufacture	2017
Top speed	114 mph
0 - 100 km/h	13.4 seconds
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	70 kW / 95 HP / 118 BHP
Max. torque	270 Nm at 1.500 rpm
Engine capacity	1.499 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	76.3 mpg
Consumption combined	68.9 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

### Internet history

#### Entry 1

Date	2021-05-26
Pictures	1
Listing price	<u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2024-06-15
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #6		2023-06-09 15:43
MOT test	number	861374931529
Result		✓ Passed
Next expi	y date	2024-06-15
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Tyre worn on in	ner edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn on	inner edge (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #5	<b>202</b>	23-06-09 08:24
MOT tes	est number	978827150366
Result		🗙 Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn on inner edge (	(5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
<b>Fail</b> (5.2.3 (d	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply (d) (i))	or cords
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Tyre worn on inner edge (5.	.2.3 (e))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4	2022-06-16 14:43
MOT test number	155323547115
Result	<b>✓</b> Passed
Advice Covers & shields fitted	

Advice Covers & shields fitted	
MOT #3	2021-06-14 13:37
MOT test number	835277630696
Result	<b>✓</b> Passed
MOT #2	2020-10-02 13:49
MOT test number	170737732324
Result	<b>✓</b> Passed
MOT #1	2019-10-31 13:26
MOT test number	548421079143
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

o met motory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO.	
***************************************	
THE PROPERTY OF THE PROPERTY O	
**********	
***************************************	
THE STREET STREET	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK STEE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-02-08
Last registration	2023-06-09
Complete history	See info



Registration #1	2017-02-08	29 mi
Registration #2	2019-10-31	9.716 mi
Registration #3	2020-10-02	13.578 mi
Registration #4		11.777 es
Registration #5		9.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	2067 mm
Height	1626 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1303 kg
Max. allowed weight	1915 kg

## Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 11/11