



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE R-DESIGN
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 6

Date	2022-02-13
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 5

Date	2021-12-15
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 4

Date	2021-10-16
Pictures	34
Listing price	View report




source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 3

Date	2021-10-04
------	------------

Pictures34

Listing priceView report



source: autotrader.co.uk

Entry 2

Date2021-07-16

Pictures33

Listing priceView report



source: cargurus.co.uk

Entry 1

Date2021-07-14

Pictures33

Listing priceView report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	27
Total items failed	17

MOT #19	2023-10-11 08:33
MOT test number	751881931126
Result	✓ Passed
Next expiry date	2024-10-10

MOT #18	2023-10-02 12:57
MOT test number	177310427732
Result	✗ Failed
Fail	Headlamp light intensity severely reduced both, poss incorrectly fitted (4.1.4 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Fail	Boot lid insecure cannot be opened but dash warning states open (6.2.1 (a) (i))
Fail	Exhaust has a major leak of exhaust gases back box (6.1.2 (a))

**MOT #17**

2023-09-08 08:52

MOT test number

617676225589

Result**✗ Failed**

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Emissions unable to be completed Major exhaust leak (8.2.2.2 (e))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Tail gate will not open allowing full inspection

Fail Exhaust has a major leak of exhaust gases Middle box (6.1.2 (a))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Heavily corroded (1.1.14 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #16

2022-08-03 11:38

MOT test number

668060223812

Result**✓ Passed**

Advice Central Rear Exhaust has a minor leak of exhaust gases exhaust box has minor blow (6.1.2 (a))

Advice Nearside Front Tyre slightly damaged/cracking or perishing tyre cracking in tread (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2022-07-13 16:43

MOT test number

898150294837

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge tyre wearing unevenly on inner edge (5.2.3 (e))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick inner and outer pads (1.1.13 (a) (ii))
- Fail** Front Windscreen washer not working both front washers not working (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking in tread (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre on 2mm tread (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 2mm tread (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Oil leaking continuously from engine posing a serious risk to road safety (8.4.1 (a) (ii))

MOT #14

2021-07-14 14:49

MOT test number

984047133359

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #13** 2020-08-21 08:03**MOT test number** 219775336344**Result** ✓ Passed**MOT #12** 2019-08-14 07:37**MOT test number** 750325272311**Result** ✓ Passed**MOT #11** 2018-09-12 12:47**MOT test number** 323463090819**Result** ✓ Passed**Advice** Plastic sill covers fitted**MOT #10** 2018-09-12 07:58**MOT test number** 734822894133**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn wish bone marked (5.3.4 (a) (i))**Advice** Plastic sill covers fitted**Fail** Nearside Front Suspension arm pin or bush excessively worn wish bone marked (5.3.4 (a) (i))**MOT #9** 2017-09-25 08:24**MOT test number** 473980978377**Result** ✓ Passed**MOT #8** 2016-09-26 08:39**MOT test number** 847204506338**Result** ✓ Passed

**MOT #7** 2016-09-26 08:39**MOT test number** 426280089322**Result** ✗ Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #6 2015-09-28 08:27**MOT test number** 550015069368**Result** ✓ Passed**MOT #5** 2014-10-03 09:31**MOT test number** 209476774235**Result** ✓ Passed**MOT #4** 2014-10-03 09:31**MOT test number** 356126274259**Result** ✗ Failed

Pass with rectification Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #3 2013-09-19 11:29**MOT test number** 986562763286**Result** ✓ Passed**MOT #2** 2013-09-19 11:29**MOT test number** 668432363216**Result** ✗ Failed

Pass with rectification Nearside Front Headlamp aim too low (1.8)

Pass with rectification Offside Front Headlamp aim too low (1.8)



MOT #1	2012-08-30 14:19
MOT test number	726643242268
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2009-09-29
Last registration	2023-10-11
Complete history	See info



Registration #1	2009-09-29	12 mi
Registration #2	2012-08-30	16.129 mi
Registration #3	2013-09-19	21.820 mi
Registration #4	2014-10-03	26.199 mi
Registration #5	2015-09-28	35.462 mi
Registration #6	2016-09-26	41.194 mi
Registration #7	2016-09-26	41.194 mi
Registration #8	2017-09-25	54.481 mi
Registration #9	2018-09-12	67.271 mi
Registration #10	2018-09-12	67.274 mi
Registration #11	2019-08-14	77.898 mi
Registration #12	2020-08-21	86.959 mi
Registration #13	2020-08-21	86.959 mi
Registration #14	2020-08-21	86.959 mi
Registration #15	2020-08-21	86.959 mi
Registration #16	2020-08-21	86.959 mi
Registration #17	2020-08-21	86.959 mi
Registration #18	2020-08-21	86.959 mi
Registration #19	2020-08-21	86.959 mi
Registration #20	2020-08-21	86.959 mi
Registration #21	2020-08-21	86.959 mi
Registration #22	2020-08-21	86.959 mi
Registration #23	2020-08-21	86.959 mi
Registration #24	2020-08-21	86.959 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	704037