



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO TSI
Colour	White
Year of manufacture	2009
Top speed	135 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-28
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-07-13
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	30
Total items failed	9

MOT #14	2021-07-14 15:41
MOT test number	931902193863
Result	✓ Passed
Next expiry date	2022-07-13

MOT #13	2020-12-02 17:57
MOT test number	581550917104
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Damage to front bumper and number plate area

**MOT #12**

2020-12-02 12:40

MOT test number

746361090998

Result

✗ Failed

Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Damage to front bumper and number plate area**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #11**

2019-12-04 11:31

MOT test number

920878341400

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10**

2018-11-28 13:42

MOT test number

333651916243

Result

✓ Passed

MOT #9

2018-11-28 11:26

MOT test number

860874292358

Result

✗ Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))



MOT #8	2017-11-27 12:16
MOT test number	214467449780
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2016-11-25 12:56
MOT test number	787019010478
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit signs of wear on inner edges (4.1.E.1)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit signs of wear on inner edge (4.1.E.1)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #6	2015-11-26 15:08
MOT test number	998520198937
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear tyre showing signs of wear on inner edges
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear tyre showing signs of wear on inner edges

**MOT #5** 2015-11-26 09:28**MOT test number** 734320987447**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear tyre showing signs of wear on inner edges**Fail** Power steering pump drive system defective drive belt is fallen apart (2.3.6)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear tyre showing signs of wear on inner edges**MOT #4** 2014-11-28 11:19**MOT test number** 749382334315**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #3** 2014-11-28 11:19**MOT test number** 117952734368**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2013-11-26 10:42**MOT test number** 507130533322**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Oil leak



MOT #1	2012-11-27 11:21
MOT test number	607122032306
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
14 May 2022

X

MOT

Expired:
13 July 2022

Tax status	Expired at 14 May 2022
Days left	716 days too late
MOT expiry date	13 July 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	PE59YVO
Plate since	2024-03-29
Current registration	PE59YVO
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-11-27
Last registration	2021-07-14
Complete history	See info



Registration #1	2009-11-27	17 mi
Registration #2	2012-11-27	13.013 mi
Registration #3	2013-11-26	18.616 mi
Registration #4	2014-11-28	25.021 mi
Registration #5	2015-11-26	33.036 mi
Registration #6	2015-11-26	33.036 mi
Registration #7	2016-11-25	38.865 mi
Registration #8	2017-11-27	51.548 mi
Registration #9	2018-11-27	65.277 mi
Registration #10	2019-11-27	79.006 mi
Registration #11	2020-11-27	92.735 mi
Registration #12	2021-11-27	106.464 mi
Registration #13	2022-11-27	120.193 mi
Registration #14	2023-11-27	133.922 mi
Registration #15	2024-11-27	147.651 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAV 101705