



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D3 SE LUX
Colour	Black
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-10-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	13
Total items failed	5

## MOT #13 2023-10-05 10:33

MOT test number 823972567571

Result ✓ Passed

Next expiry date 2024-10-24

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #12 2023-10-04 09:24

MOT test number 101818179886

Result ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Headlamp levelling device inoperative (4.1.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #11 2022-10-25 14:38

MOT test number 489510513907

Result ✓ Passed**Advice** Offside Rear lamp damaged

**MOT #10** 2022-10-25 11:00**MOT test number** 325620651714**Result** ✗ Failed**Fail** Rear Registration plate inscription illegible deteriorated (0.1 (b))**Advice** Offside Rear lamp damaged**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #9** 2021-10-19 13:16**MOT test number** 791697752744**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2020-10-03 06:59**MOT test number** 634382732239**Result** ✓ Passed**MOT #7** 2019-04-16 12:03**MOT test number** 401707473483**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2018-04-20 10:03**MOT test number** 572094157316**Result** ✓ Passed**Advice** Oil on min



MOT #5	2017-04-24 13:09
MOT test number	197229192806
Result	✓ Passed
MOT #4	2016-05-10 11:30
MOT test number	938737446733
Result	✓ Passed
MOT #3	2015-05-11 15:42
MOT test number	636571435103
Result	✓ Passed
MOT #2	2014-05-06 09:35
MOT test number	918856324138
Result	✓ Passed
MOT #1	2014-05-02 15:47
MOT test number	866372224121
Result	✗ Failed
Fail	Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
Fail	Nearside Headlamp cleaning device inoperative (1.7.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-31
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2011-05-31	23 mi
Registration #2	2014-05-02	35.802 mi
Registration #3	2014-05-06	35.802 mi
Registration #4	2015-05-11	47.672 mi
Registration #5	2016-05-10	56.624 mi
Registration #6	2017-04-24	64.648 mi
Registration #7	2018-04-20	72.883 mi
Registration #8	2019-04-16	83.437 mi
Registration #9	2020-05-20	95.277 mi
Registration #10	2021-05-20	107.277 mi
Registration #11	2022-05-20	119.277 mi
Registration #12	2023-05-20	131.277 mi
Registration #13	2024-05-20	143.277 mi
Registration #14	2025-05-20	155.277 mi
Registration #15	2026-05-20	167.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1672 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1028850