



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Blue
Year of manufacture	2006
Top speed	142 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	206 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-01
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-29
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	32
Total items failed	18

MOT #21	2023-03-31 13:43
MOT test number	616709544279
Result	✓ Passed
Next expiry date	2024-04-29
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2022-04-21 08:09
MOT test number	495185932376
Result	✓ Passed

MOT #19	2021-04-30 11:18
MOT test number	456322253075
Result	✓ Passed

MOT #18	2021-04-29 13:00
MOT test number	410441936910
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #17**

2020-04-20 08:01

MOT test number

619398143750

Result

✓ Passed

Advice Headlights dim**Advice** Front tyres wearing on outer edges**MOT #16**

2020-04-16 08:46

MOT test number

779423044938

Result

✗ Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Front tyres wearing on outer edges**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Advice** Headlights dim**MOT #15**

2019-04-30 13:56

MOT test number

509222688169

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2019-04-26 15:08

MOT test number

408395726978

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt Front arm (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn Rear arm (5.3.4 (a) (i))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #13

2018-06-04 09:22

MOT test number

487220794498

Result**✓ Passed****MOT #12**

2017-06-14 15:05

MOT test number

151958034116

Result**✓ Passed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front have wear (3.5.1i)
- Advice** Headlamp deteriorated but light output not reduced both lens faded/beam image poor (1.7.5a)
- Advice** Offside Rear Brake pipe slightly corroded early stages (3.6.B.2c)

**MOT #11** 2016-06-22 10:25**MOT test number** 549941046981**Result** ✓ Passed**MOT #10** 2016-01-25 15:51**MOT test number** 702617364945**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #9** 2016-01-25 12:33**MOT test number** 336743363132**Result** ✗ Failed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-12-15 14:49**MOT test number** 409829144373**Result** ✓ Passed**MOT #7** 2014-01-08 15:52**MOT test number** 637408504003**Result** ✓ Passed

**MOT #6** 2013-03-16 16:33**MOT test number** 459255773067**Result** ✓ Passed**MOT #5** 2012-03-21 14:23**MOT test number** 356491382021**Result** ✓ Passed**Notice** Nearside rear tyre damaged on outer wall.**Notice** Both rear tyres starting to wear low.**MOT #4** 2011-03-14 14:25**MOT test number** 328663071013**Result** ✓ Passed**MOT #3** 2010-03-16 16:41**MOT test number** 861095070024**Result** ✓ Passed**Notice** Oil leak**Notice** O/s/f & n/s/f thrust arm bush starting to split**MOT #2** 2010-03-16 16:41**MOT test number** 572505670027**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (1.8)**Notice** O/s/f & n/s/f thrust arm bush starting to split**Pass with rectification** Offside Headlamp aim too low and too far to the left. (1.8)**Notice** Oil leak



MOT #1	2009-03-18 14:21
MOT test number	670077679074
Result	✓ Passed
Advice	Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
29 April 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 RK06XAU
Plate since	2024-03-29
Current registration	 RK06XAU
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-21
Last registration	2023-03-31
Complete history	See info



Registration #1	2006-03-21	6 mi
Registration #2	2009-03-18	17.991 mi
Registration #3	2010-03-16	24.137 mi
Registration #4	2011-03-14	30.406 mi
Registration #5	2012-03-21	37.337 mi
Registration #6	2013-03-16	44.713 mi
Registration #7	2014-01-08	49.807 mi
Registration #8	2014-12-15	53.476 mi
Registration #9	2016-01-25	54.418 mi
Registration #10	2016-01-25	54.418 mi
Registration #11	2016-06-22	54.587 mi
Registration #12	2016-06-22	54.587 mi
Registration #13	2016-06-22	54.587 mi
Registration #14	2016-06-22	54.587 mi
Registration #15	2016-06-22	54.587 mi
Registration #16	2016-06-22	54.587 mi
Registration #17	2016-06-22	54.587 mi
Registration #18	2016-06-22	54.587 mi
Registration #19	2016-06-22	54.587 mi
Registration #20	2016-06-22	54.587 mi
Registration #21	2016-06-22	54.587 mi
Registration #22	2016-06-22	54.587 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1615 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030523672