



report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE V6 SE
Colour	Silver
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	37.2 mpg
Consumption combined	27.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-09
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #19	2020-09-19 09:36
MOT test number	423779903527
Result	✓ Passed
Next expiry date	2021-09-18
Advice	Front brake discs corroded
Advice	Oil leak

MOT #18	2019-09-18 11:11
MOT test number	619091072300
Result	✓ Passed
Advice	Oil leak
Advice	Front brake discs corroded
Advice	Both front tyres worn inner edge

MOT #17	2018-09-10 08:08
MOT test number	571102516512
Result	✓ Passed
Advice	Engine oil leak
Advice	Front brake discs worn
Advice	Sill kit fitted
Advice	Inner sills corroding
Advice	Rear brake discs corroded

**MOT #16**

2018-09-06 15:26

MOT test number

870955865184

Result**✗ Failed**

- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Anti-roll bar linkage insecurely attached droplink (5.3.3 (a) (i))
- Advice** Engine oil leak
- Advice** Front brake discs worn
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Sill kit fitted
- Fail** Emissions not tested (8.2.1.2 (d))
- Advice** Inner sills corroding
- Advice** Rear brake discs corroded

MOT #15

2017-07-17 14:58

MOT test number

771735078214

Result**✓ Passed**

- Advice** Front brake pads worn
- Advice** Nearside Rear tyre worn close to limit
- Advice** Sill kit fitted
- Advice** Offside Front tyre worn edges
- Advice** Offside Rear tyre worn
- Advice** Nearside Front tyre worn edges low inner edge
- Advice** Offside Front tyre worn edges



MOT #14	2016-07-16 11:15
MOT test number	584307458857
Result	✓ Passed
Advice	Rear brake discs corroded
Advice	Sill kit fitted

MOT #13	2015-07-09 15:29
MOT test number	168760295190
Result	✓ Passed
Notice	Oil leak
Notice	Engine management light on
Advice	Offside Rear coil spring corroded (2.4.C.1b)
Notice	Sill covers fitted
Advice	Nearside Rear coil spring corroded (2.4.C.1b)
Notice	Handbrake travel could be better
Advice	Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #12**

2015-07-07 10:52

MOT test number

667128085191

Result**✗ Failed**

- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Notice** Engine management light on
- Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Oil leak
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Road wheel cracked (4.2.A.1a)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Notice** Sill covers fitted
- Notice** Handbrake travel could be better
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Road wheel cracked (4.2.A.1a)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #11

2014-07-08 07:40

MOT test number

178009284120

Result**✓ Passed**

- Notice** Both Rear brake discs are corroded on the inside faces

**MOT #10**

2014-07-08 07:40

MOT test number

998019284109

Result

✗ Failed

Pass with rectification Nearside Stop lamp not working (1.2.1b)**Notice** Both Rear brake discs are corroded on the inside faces**MOT #9**

2013-06-27 16:07

MOT test number

465208273182

Result

✓ Passed

Notice General surface corrosion to exhaust system in places.**Notice** Engine oil leaks.**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8**

2013-06-27 12:39

MOT test number

457668273174

Result

✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** General surface corrosion to exhaust system in places.**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Engine oil leaks.**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**MOT #7** 2012-06-25 16:20**MOT test number** 107597772131**Result** ✓ Passed**MOT #6** 2012-06-25 09:42**MOT test number** 175557272159**Result** ✗ Failed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #5** 2011-07-02 14:44**MOT test number** 705373781155**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Slight play rear inner anti roll bar bushes**Notice** Rear discs slightly corroded**Notice** Front discs corroded**Notice** Door sill covers fitted**MOT #4** 2010-11-11 12:40**MOT test number** 533325010374**Result** ✓ Passed**Notice** Rear discs corroded**Notice** Front discs corroded**Notice** Door sill covers fitted**Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)

**MOT #3** 2010-11-11 12:27**MOT test number** 214125410398**Result** ✗ Failed**Notice** Front discs corroded**Notice** Door sill covers fitted**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)**Notice** Rear discs corroded**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #2** 2010-01-15 09:39**MOT test number** 203555910037**Result** ✓ Passed**Advice** Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2008-06-27 11:43**MOT test number** 541999478156**Result** ✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-06-30
Last registration	2020-09-19
Complete history	See info



Registration #1	2005-06-30	17 mi
Registration #2	2008-06-27	31.411 mi
Registration #3	2010-01-15	36.578 mi
Registration #4	2010-11-11	39.026 mi
Registration #5	2010-11-11	39.026 mi
Registration #6	2011-07-02	46.559 mi
Registration #7	2012-06-25	53.540 mi
Registration #8	2012-06-25	53.541 mi
Registration #9	2013-06-27	563.328 mi
Registration #10	2013-06-27	56.338 mi
Registration #11	2013-06-27	56.338 mi
Registration #12	2013-06-27	56.338 mi
Registration #13	2013-06-27	56.338 mi
Registration #14	2013-06-27	56.338 mi
Registration #15	2013-06-27	56.338 mi
Registration #16	2013-06-27	56.338 mi
Registration #17	2013-06-27	56.338 mi
Registration #18	2013-06-27	56.338 mi
Registration #19	2013-06-27	56.338 mi
Registration #20	2013-06-27	56.338 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1595 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	506129414XB