





General information Make CITROEN Model C4 GRAND PICASSO GRAND PURETECH FLAIR S/S Colour Red Year of manufacture 2017 **Top speed** 125 mph 0 - 60 mph 10.8 seconds Gearbox 6 speed Manual

Engine & fuel consumption

| Power | 129 BHP |
|-------------------------|---------------------|
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 116 g/km |
| CO2 label | С |







Internet history

| Entry 2 | |
|----------|------------|
| Date | 2021-09-18 |
| Pictures | 12 |

Listing price

_

View report



source: cargurus.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-09-16 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-07-03 |
|--------------------|------------|
| MOT pass rate | 57 % |
| MOT passed | 4 |
| Failed MOT tests | 3 |
| Total advice items | 14 |
| Total items failed | 0 |

| MOT #7 | 2023-07-04 14:12 |
|------------------|------------------|
| MOT test number | 516358776778 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-03 |

| MOT #6 | | 2023-07-03 15:19 |
|----------|--|------------------|
| MOT test | number | 657956304670 |
| Result | | 🗙 Failed |
| MAJOR | Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |

| MOT #5 | 2022-06-07 17:08 |
|-----------------|------------------|
| MOT test number | 475339885785 |
| Result | ✓ Passed |





| MOT #4 | | 2022-06-07 07:34 |
|----------------|---|------------------|
| MOT test numbe | er | 935676671334 |
| Result | | 🗙 Failed |
| MAJOR Near | side Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| DANGEROUS | Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |
| DANGEROUS | Offside Rear Tyre has ply or cords damaged 205/55/R17 (5.2.3 (d) (ii)) | |
| Advice Near | side Rear Child Seat fitted not allowing full inspection of adult belt | |
| MAJOR Rear | Brake pad(s) worn down to wear indicator (1.1.13 (a) (i)) | |
| DANGEROUS | Nearside Rear Tyre has ply or cords damaged 205/55/R17 (5.2.3 (d) (ii)) | |

| MOT #3 | 2021-06-22 11:10 |
|-----------------|------------------|
| MOT test number | 797674246242 |
| Result | ✓ Passed |

| MOT #2 | 2020-06-25 14:37 |
|--|--------------------------------|
| MOT test number | 743640360357 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge bold on in (e)) | nside and outside edges (5.2.3 |





| MOT #1 | 2020-06-25 09:36 |
|---|------------------|
| MOT test number | 706408425208 |
| Result | 🗙 Failed |
| MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |
| DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Minor Nearside Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Minor Offside Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 October 2024 | ✓ MOT Expires: 3 July 2024 |
|--|-------------------------------------|
| Tax status | Valid until 1 October |
| Days left | 155 |
| MOT expiry date | 3 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---------|-------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| Date | | · · · |
| Category | 1000000 | AMPL |
| Туре | | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2017-07-04 |
| Last registration | 2023-07-04 |
| Complete history | See info |



| Registration #1 | 2017-07-04 | 27 mi |
|------------------|------------|------------|
| Registration #2 | 2020-06-25 | 23.708 mi |
| Registration #3 | 2020-06-25 | 23.708 mi |
| Registration #4 | 2021-06-22 | 32.404 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 10.300 est |

More info >





| Safety ratings | | |
|------------------------|-----------------|-----------------------|
| NCAP rating | **** | |
| Video | see crash video | |
| Dimensions & weight | | |
| Width | | 1826 mm |
| Height | | 1644 mm |
| Length | | 4597 mm |
| Wheel base | | 2840 mm |
| Kerb weight | | 1297 kg |
| Max. allowed weight | | 2125 kg |
| Additional information | | |
| Fuel tank capacity | | 57 I |
| Fuel delivery | | Multi-Point Injection |
| Number of doors | | 5 |
| Number of seats | | 7 |
| Number of axles | | 2 |
| Engine number | | XTA10721394 |